

**Operating instructions
Digital handheld
pressure gauge**




HM35

Operating Instructions

Contents

| | |
|--|----|
| Operating Elements | 2 |
| 1 Description | 3 |
| 2 Safety information | 3 |
| 3 Operation | 4 |
| 3.1 Switching on and off | 4 |
| 3.2 Lighting | 5 |
| 3.3 Pneumatic connection | 5 |
| 3.4 Functions and operating modes | 6 |
| 3.5 Menu selection and set-up | 6 |
| 3.6 Data logging | 9 |
| 3.6.1 Data recording | 9 |
| 3.6.2 Transfer of data to a PC | 10 |
| 3.6.3 Deleting data | 10 |
| 3.7 Communication | 10 |
| 3.7.1 IR/RS232-Protocol | 10 |
| 3.7.2 IR-Hardware of the instrument | 12 |
| 3.8 Battery replacement | 19 |
| 3.9 Calibration | 19 |
| 4 Specifications | 20 |
| 4.1 Technical data | 20 |
| 4.2 Measuring Range and Precision | 22 |
| 4.3 Measurement units | 23 |
| 4.4 Mains supply unit connection | 24 |
| 5 Maintenance and storage | 24 |
| 6 Warning messages and faults | 24 |
| 7 Accessories | 25 |
| 8 Summary of technical characteristics | 25 |

Operating Elements



Please note this warning symbol in these operating instructions!

EC Declaration of Conformity

We declare on our own responsibility that this product conforms to the following standards:

- EN 61326-1/A1

Copyright ©

The contents of this publication may not be copied without the express permission of the manufacturer. We reserve the right to make dimensional and design changes.

1 Description

The HM35 digital pressure gauge is a pressure-measuring instrument with an integrated pressure sensor for the measurement of differential, relative or absolute pressures and vacuum. Its versatile range of functions and high precision render it suitable for a wide range of applications. Via the infrared interface (IR) and SCPI (**S**tandard **C**ommands for **P**rogrammable **I**nstruments) commands, the HM35 can communicate with a PC. Its operation is very simple, and supports the user in his measurement tasks.

Operating modes

- Pressure measurement / Differential pressure
- Min./Max. values
- Mean value (average)
- Pressure change rate
- Data logging

Selectable configuration possibilities

- Data logging
→ Interval time, print/transfer, deleted memory
- Configuration
→ Measurement units, display filter, auto. switch-off time, auto zero, lighting level, etc.
- Average period (period for determining average value)
- Date and Time (real-time clock)
- Calibration
→ Date of last calibration date, manual recalibration

2 Safety information

- **The pressure values and overload levels** stated on the rating plate and quoted in these operating instructions **must not be exceeded**, as otherwise the **pressure sensor could be destroyed** or there could be a **risk of injury**.
- Only use pressure hoses with a maximum loading capacity corresponding to that necessary for the application.
- Ensure that the pneumatic hoses are securely fitted! Do not use damaged or kinked hoses.
- Do not open up the instrument (this would void the guarantee).
- The instrument must be stored within the permissible storage temperature range.




The instrument must not be put into operation in an explosive environment!




Wear eye protection if working with pressures > 1bar!

3 Operation

3.1 Switching on and off

Switching on Briefly press the **On/Off** key () (< 1 s)

For precise measurements, the HM35 must first be switched on for at least 1 minute (warm-up phase).


Switching off Briefly press the **On/Off** key () (< 1 s),

or

automatic switch-off 3, 10 or 60 minutes after the last time key operation (automatic switch-off does not take place during Average, Change Rate and Data Logging measurements or in IR and network operation).

Notes

- The HM35 switches on automatically when the supply voltage is connected.
- The HM35 continues to work in battery mode following an interruption of the supply voltage
- In case of a change in temperature, the HM35 must be allowed to adapt to the new ambient temperature for a least 30 minutes while switched off in order to attain the best measurement accuracy.
- The day/time, battery level and accuracy will be briefly displayed at switch on:




- After switch-on, the HM35 switches to the last operational mode used, e.g.:




- With the display filter activated, wait until the transient effect finishes (approx. 5 s).

3.2 Lighting

Switching on Press the **On/Off-key** () for > 1 s

Brightness control In the **Menu**, select the **Configuration** → **Lighting** function and select an adjustment of **Off**, **Level 1**, **Level 2** or **Level 3**.

Switching off Briefly press the **On/Off key** () (< 1 s)
(switch off the instrument),
or automatic switch-off after 20 s.
With mains operation, the HM35 must be switched off manually.

3.3 Pneumatic connection

| Designation | Pressure range |
|--|----------------|
| Hose 4/6 mm | ≤ 7,5 bar |
| NPT1/8" internal | 10 ... 90 bar |
| Plug in nipple „Rectus“ Type 20 | ≤ 30 bar |
| M10 x 1 internal thread (for „Minimess“ connector) | all |

Ensure that the pneumatic hoses are connected correctly!

- +P** Higher pressure
- S-** Lower pressure (not available with the absolute and relative pressure version)




When screwing onto a coupling, it is important to hold the coupling steady with a wrench to prevent any turning!

Never secure by holding the casing itself!



3.4 Functions and operating modes

| Key | | clear | hold |  ¹⁾ | Start ²⁾ |
|-----|----------------------------------|---|--|---|---------------------|
| | Functions | | | | |
| | PRESSURE | Zero: sets measured value to zero ³⁾ | Freezes all current measurement values | To Menu selection | -- |
| | DIFFERENCE | | | | |
| ▲ | MIN/MAX | Sets Max/Min to current measured value | | Stop/Menu | Starts measuring |
| ▼ | AVERAGE ⁴⁾ | Sets measured value to zero ³⁾ | | | |
| | CHANGE RATE ⁵⁾ | | -- | | |
| | DATA LOGGING | | | | |

Notes

- 1) Once a measurement procedure has been started, the menu selection is blocked.
- 2) During a measurement procedure (after Start has been pressed), you can switch between functions. This permits, for example, the observation of the Min/Max function during data logging.
- 3) The Clear key has no function in the absolute pressure instruments.
- 4) The AVERAGE function creates an arithmetic average value of all measured values during the time period selected in the menu. After expiry of the time period, the average value will be displayed.
- 5) Measurement of the leak rate (diff/gauge sensor) or tendency (abs. sensor). The pressure change (CHANGE RATE) from the start time to the current time will be displayed. The first display occurs 10 s after the start.

3.5 Menu selection and set-up

Navigation within the Menu selection

| | | |
|-------|-------------------------------|--|
| clear | Brief (< 1 s) | 1 level back |
| | Long (> 1 s) | Back to the function level/operating modes |
| ▲ ▼ | Selection of Set-up/Functions | |

The functions shown inverted on the display will be carried out if the **Function** key () is pressed.

The currently selected setting for values is marked with '✓'. In the following table, the default values are correspondingly marked (factory settings).

| Key | | | | Notes |
|-----|---------------|--------------------|--------------------|-------------------------|
| | Data logging | | | |
| | | Interval | | Interval period |
| | | | manual | |
| | | | 25 M./s | |
| | | | 10 M./s | |
| | | | 1 s | |
| | | | ✓ 2 s | |
| | | | 5 s | |
| | | | 10 s | |
| | | | 30 s | |
| | | | 1 min | |
| | | | 2 min | |
| | | | 5 min | |
| | | | 10 min | |
| | | | 30 min | |
| | | | 1 h | |
| | | | 3 h | |
| | | | 6 h | |
| | | | 12 h | |
| | | | 24 h | |
| | | | user | Set with ▲/▼/ EDIT/OK |
| ▲ | | Print Data Logging | | |
| ▼ | | | Press 'Start' | Print/send via IR |
| | | Clear Memory | | |
| | | | Press 'Clear' | Deletes the data memory |
| | Configuration | | | |
| | | Pressure Unit | | |
| | | | ✓ mbar | |
| | | | bar | |
| | | | Pa | |
| | | | hPa | |
| | | | kPa | |
| | | | MPa | |
| | | | kg/cm ² | |
| | | | kg/m ² | |
| | | | mmHg | |
| | | | cmHg | |
| | | | mHg | |
| | | | inHg | |
| | | | mmH ₂ O | |
| | | | cmH ₂ O | |
| | | | mH ₂ O | |
| | | | inH ₂ O | |
| | | | ftH ₂ O | |
| | | | psi | |
| | | | lb/in ² | |
| | | | lb/ft ² | |
| | | | torr | |
| | | | atm | |

| Key | | | | Notes |
|-----|----------------|-----------------------|-----------|---|
| | | Display Filter | | Filters the display values 1) |
| | | | ✓ On | |
| | | | Off | |
| | | Auto-Off | | Auto. switch-off |
| | | | 3 min | |
| | | | ✓ 10 min | |
| | | | 60 min | |
| | | Auto-Zero | | |
| | | | On | Sensor auto-zeros at switch-on if measured value < 1% FS |
| | | | ✓ Off | |
| | | Beep | | Warning beeper |
| | | | ✓ On | |
| | | | Off | |
| | | Lighting | Off | |
| | | | Level 1 | Only Level 1 possible for Ex-models |
| | | | Level 2 | |
| ▲ | | | ✓ Level 3 | |
| ▼ | | IR Interface | | |
| | | | ✓ On | At switch-on, the automatic connection to the PC is activated for 2 minutes |
| | | | Off | Automatic connection is de-activated |
| | Average period | | | Time period for average value |
| | | 10 s | | |
| | | 30 s | | |
| | | 1 min | | |
| | | 2 min | | |
| | | ✓ 5 min | | |
| | | 10 min | | |
| | | 30 min | | |
| | | 1 h | | |
| | | 3 h | | |
| | | 6 h | | |
| | | 12 h | | |
| | | 24 h | | |
| | | user | | Set with ▲/▼/EDIT/OK |
| | Date & Time | | | |
| | | dd.mm.yyyy | | Set with ▲/▼/ EDIT/OK |
| | | hh:mm:ss | | Set with ▲/▼/ EDIT/OK |
| | Calibration | | | |
| | | History | | Displays the last calibration date |
| | | Manual re-calibration | | Manual re-calibration of the zero point and limit value |

Note

- 1) With the filter function active, short-term measurement variations should be suppressed, resulting in a steadier display. Measured values via the interface and in the Data Logging Memory will not be filtered.

3.6 Data logging

3.6.1 Data recording

Every time that the Data Logging is started, an information header ("**Header**") will first be saved: The measured values will then be saved sequentially. "**Stop**" will be saved after every interruption of the logging or if manual storage is carried out. At the end of all the data loggings, "**End**" will be saved. Measured values can be uniquely identified by their header.

| Designation | Example 1 | Data Logging | Type of Data ²⁾ |
|-------------|-------------|----------------------------------|----------------------------|
| Date | 01.01.2001 | Header | INTEGER |
| Time | 12:00:00 | | |
| Interval | 30 s | | |
| Function | PRESS | | |
| Unit | mbar | | |
| | 1000.0 | Measurement series ¹⁾ | FLOAT |
| | 1001.1 | | |
| | 1001.5 | | |
| | 1000.3 | | |
| | 999.7 | | |
| | Stop | | DISCRETE |
| | End | | DISCRETE |

| Designation | Example 2 | Manual saving | Type of Data ²⁾ |
|-------------|-------------|----------------------------------|----------------------------|
| Date | 01.01.2001 | Header 1st measurement | INTEGER |
| Time | 12:00:00 | | |
| Interval | Manual | | |
| Function | PRESS | | |
| Unit | inHg | | |
| | 29.92 | 1st measured value ¹⁾ | FLOAT |
| | Stop | | DISCRETE |
| | | | |
| Date | 01.01.2001 | Header 2nd measurement | INTEGER |
| Time | 12:00:33 | | |
| Interval | Manual | | |
| Function | PRESS | | |
| Unit | inHg | | |
| | 29.29 | 2nd measured value ¹⁾ | FLOAT |
| | Stop | | DISCRETE |
| | | | |
| Date | 01.01.2001 | Header 3rd measurement | INTEGER |
| Time | 12:01:45 | | |
| Interval | Manual | | |
| Function | PRESS | | |
| Unit | inHg | | |
| | 28.00 | 3rd measured value ¹⁾ | FLOAT |
| | Stop | | DISCRETE |
| | End | | DISCRETE |

Notes

- 1) „Over“ (data type DISCRETE) for invalid pressure value
- 2) For the Data Type key, refer to the table on Page 18.
- 3) User-interval period will, for example, be displayed as follows, “user 01:15:00”

3.6.2 Transfer of data to a PC

(with HM35 Communication Software)

1. Install the IR (IrDA) -adapter according the instructions of the manufacturer.
2. Install the HM35 Communication Software.
3. Start the HM35 Communication Software.
4. Place the instrument max. 20 cm from the IR (IrDA)-Adapter and switch it on. Ensure a line-of sight connection between instrument and IR-adapter!
If there is no communication with the instrument for more than 2 minutes, the IR interface of the instrument turns off automatically! By restarting the instrument the IR interface is reactivated.

3.6.3 Deleting data

1. In the **Menu**, select the **Data Logging** → **Clear Memory** function.
2. Press the **Clear** key.

3.7 Communication

3.7.1 IR/RS232-Protocol

COM-Port Settings

| | |
|-----------|------|
| Baudrate | 9600 |
| Data bits | 8 |
| Parity | no |
| Protocol | no |
| Stop bit | 1 |

Communication Protocol

Coding

The characters are transferred as ASCII-Code.

Sending a command from PC to the instrument

<SCPI Command> [SP <Parameter 1>] [, <Parameter 2>] [, <Parameter 3>] [, ...]
 HT [* <CS>] CR

Examples:

Setting the time to 07:08:09:

S Y S T : T i m e S P 0 7 , 0 8 , 0 9 H T * 2 5 5 CR (with checksum)
 S Y S T : T i m e S P 0 7 , 0 8 , 0 9 H T CR (without checksum)

Reading the time:

S Y S T : T i m e ? H T * 1 4 2 CR (with checksum)
 S Y S T : T i m e ? H T CR (without checksum)

Response from instrument to PC

<Return Value 1> [, <Return Value 2>] [, <Return Value 3>] [, ...] HT * <CS> CR

SCPI Command: SCPI command according the table on following pages
 CS: Checksum
 Return Value: Response from instrument
 [] Option

| ASCII-character | Hex-Code | Meaning |
|-----------------|----------|-----------------------|
| SP | 0x20 | Space |
| HT | 0x09 | Horizontal Tabulation |
| CR | 0x0D | Carriage Return |
| * | 0x2A | Asterisk |
| , | 0x2C | comma |

SCPI Commands

There is no difference between small and capital letters.

Checksum (CS)

The use of the checksum is optional. A * indicates a following checksum. The ASCII-character * is included in the calculation of the checksum. The checksum is calculated from the low byte.

Example:

Reading the date

S Y S T : D a t e ? H T *
 53 59 53 54 3A 44 61 74 65 3F 09 2A hex
 83 89 83 84 58 68 97 116 101 63 09 42 dez

sum: 37D hex low byte: 7D hex
 893 dez 125 dez

The checksum is 125 decimal.

Command:

S Y S T : D a t e ? H T * 1 2 5 CR (with checksum)
 S Y S T : D a t e ? H T CR (without checksum)

Return Value

Command processed:

Return Value = o k

Example for response: o k HT * 1 3 CR

Error

| Return Value | Meaning |
|--------------|--|
| er-001 | RS232 Protocol checksum Error |
| er-110 | Header Error; Too short Header Error; Too many subnodes Header Error; Query not at leaf node Header Error; Multiple queries Header Error; Characters after query Header Error; Too long |
| er-113 | Undefined Header; Undefined command |
| er-109 | Missing parameter Missing parameter; Boolean expected Missing parameter; String expected Missing parameter; Discrete expected Missing parameter; Not of expected type |
| er-101 | Invalid character; Terminator expected |
| er-108 | Invalid parameter; Out of bounds Invalid parameter; Too long |
| er-203 | Command Protected |
| er-999 | EEProm Read/Write Error |
| er-002 | Fatal Command Execution Error |

Example: Checksum Error

Response: e r - 0 0 1 HT * 200 CR

After command with response value

Example: reading time (07:08:09)

Response: 0 7 , 0 8 , 0 9 HT * 1 9 5 CR

| |
|---|
| After every command wait for the response of the instrument (max. 680 ms). |
|---|

3.7.2 IR-Hardware of the instrument


The **hardware** of the IR-connection of the instrument is compatible with **IrDA-Standard 1.0**.

IR (IrDA)- Adapter

A **passive IrDA-adapter** has to be used which is compatible to **IrDA-Standard 1.0**. The IrDA adapter ACT-IR220Lplus is available as accessory.

The following explanations apply to this type:


Initialisation



Remarks

ACT-220L/220L+ are programmed by toggling the control lines RTS and DTR. These lines may not be low at the same time during operation. In this condition the ACT-220L/220L+ goes in power down mode. If DTR and RTS are low at the same time or in an undefined condition, both lines must be set high for at least 50 ms to leave the power down mode.

Setting the baudrate



Remarks

Before setting the baudrate the ACT-220L/220L+ has to be initialised according **Initialisation**. The baudrate is set to 9600 bps according the opposite diagram. A PC usually needs more than 0.5 us for an I/O-Instruction.

Control commands

The control commands are largely defined by the **Standard Commands for Programmable Instruments (SCPI)**.

| Command | Sub-node 1 | Sub-node 2 | Transfer Parameters | Parameter Data Type |
|----------------|---------------|------------|---------------------|---------------------|
| MEASure | :PRESsure | | <interval> | INTEGER |
| | :PRESsure? | | --- | --- |
| | :TEMPerature? | | --- | --- |
| UNITs | :PRESsure | | <unit> | DISCRETE |
| | :PRESsure? | | --- | --- |
| SYSTEM | :DATE | | <yyyy>,<mm>,<dd> | INTEGER |
| | :DATE? | | --- | --- |
| | :TIME | | <hh>,<mm>,<ss> | INTEGER |
| | :TIME? | | --- | --- |
| | :ERRor | [NEXT]? | --- | --- |
| | :VERSion? | | --- | --- |
| | :BEEPer | :STATe | <state> | BOOLEAN |
| | :BATTery? | | --- | --- |
| | :RANGe? | | --- | --- |
| | :TOLerance? | | --- | --- |
| | :IDENT? | | --- | --- |
| | :SET | :FILTer | <state> | BOOLEAN |
| | | :ZERO | --- | --- |

| Parameter limits | Feedback data | Feedback data type | Description | Remarks |
|---|--|--------------------|--|--|
| 0, 10, 25 | <value> | FLOAT | Continuous transfer of measured values | Continuous measurement with 10 or 25 M/s. Stops with Interval=0 |
| --- | <value> | FLOAT | Query measured pressure value | Individual value |
| --- | <value> | FLOAT | Query sensor temperature | °C, individual value |
| mbar, bar,.... atm | --- | --- | Pressure unit input | |
| --- | <unit> | DISCRETE | Query pressure unit | E.g., mbar, bar,.... atm |
| yyyy: 2001 ...2099 mm: 1...12 dd: 1... xx | --- | --- | Input date | yyyy: year, mm: month dd: day |
| --- | <yyyy>,<mm>,<dd> | INTEGER | Query date | yyyy: year, mm: month dd: day |
| 0...23, 0...59, 0...59 | --- | --- | Input time | hh: hours, mm: minutes ss: seconds |
| --- | <hh>,<mm>,<ss> | INTEGER | Query time | hh: hours, mm: minutes ss: seconds |
| --- | <Error_number>, "<Error_description> (;<Device-dependent info>)" | INTEGER, STRING | Query SCPI Error Queue | STRING with ,fixed text' and optional ,free text', separated by a semicolon, maximum 255 digits |
| --- | <version> | FLOAT | SCPI query and firm- ware version | e.g. '2001.0' , 'FW:300' |
| ON, OFF | --- | --- | Beeper enable / disable | |
| --- | <value> | INTEGER | Query battery state | Range 0...100, value in % |
| --- | <range> | STRING | Query sensor measurement range (in mbar) | e.g. "1,000 mbar" |
| --- | <tolerance> | STRING | Query sensor tolerance | e.g. '0.05 %FS' |
| --- | <type, MOD, S/N> | STRING | Query instrument identification | e.g. "HM3500DLH200, MOD00A,1234567" |
| ON, OFF | --- | --- | Set filter for display | |
| --- | --- | --- | Zero measure pressure value (ZERO) | |

| Command | Sub-node 1 | Sub-node 2 | Transfer parameter | Parameter data type |
|---------------|------------|------------|--------------------|---------------------|
| SYSTEM | :SET | :AOFF | <time> | DISCRETE |
| | | :OFF | --- | --- |
| | | :AZERo | <state> | BOOLEAN |
| | | :INTerval | <interval> | DISCRETE |
| | | :AVERage | <interval> | DISCRETE |
| | :CONFig | :IRDA | <status> | BOOLEAN |

| | | | | |
|-------------------|----------|--|-----|-----|
| DIAGnostic | :ERRors? | | --- | --- |
|-------------------|----------|--|-----|-----|

| | | | | |
|----------------|-------------|--|---------|----------|
| DISPlay | :BRIGhtness | | <level> | DISCRETE |
|----------------|-------------|--|---------|----------|

| | | | | |
|---------------|---------|--------|-----|-----|
| MEMory | :COPY | :DLOG? | --- | --- |
| | :DElete | :ALL | --- | --- |

| | | | | |
|--------------|--|--|-----|-----|
| *CLS | | | --- | --- |
| *IDN? | | | --- | --- |
| *STB? | | | --- | --- |
| *TST? | | | --- | --- |
| *RST | | | --- | --- |

| Parameter limits | Feedback data | Feedback data type | Description | Remarks |
|----------------------------|---------------|--------------------|------------------------------------|-----------------|
| 3min, 10min, 60min | --- | --- | Set auto Off time | |
| --- | --- | --- | Switch off instrument | |
| ON, OFF | --- | --- | Enable/disable auto zero | |
| 25M./s, 10M./s, 1s ... 24h | --- | --- | Set interval time for Data Logging | Similar to Menu |
| 10s, 30s ... 24h | --- | --- | Set time period for Average | Similar to Menu |
| OFF | --- | --- | Set auto IrDA connection | |

| | | | | |
|-----|----------------------|----------|----------------------------|--|
| --- | <err>,<err>,<err>... | INTEGER | Query the BIT-Error memory | Variable amount of Feedback data, err: 0...255 |
| | <message> | DISCRETE | Query the BIT-error memory | If Error memory deleted: 'No Errors!' |

| | | | | |
|--------------------------------|-----|-----|--------------------------------------|---|
| OFF, level 1, level 2, level 3 | --- | --- | Brightness setting for LCD backlight | EX-instrument only OFF and Level 1, similar to Menu |
|--------------------------------|-----|-----|--------------------------------------|---|

| | | | | |
|-----|--------|---------|-------------------------------------|-------------------------------------|
| --- | <data> | diverse | Select Memory Data Logging (cyclic) | Complete reading, Format: see 3.6.1 |
| --- | --- | --- | Delete Memory Data Logging | |

| | | | | |
|-----|------------------|---------|---------------------------------|-----------------|
| --- | --- | --- | Delete Status and Error Memory | |
| --- | <type, MOD, S/N> | STRING | Query instrument identification | See SYST:IDENT? |
| --- | <data> | INTEGER | Query Status Byte | |
| --- | <data> | INTEGER | Initiate a Self-Test | |
| --- | --- | --- | Reset command | |

Data Type Key

| Designation | Description | Example |
|-------------|---|--------------------------------------|
| INTEGER | Decimal number, whole numbers only | 123 |
| FLOAT | Floating-point number | 123.45 |
| I-FLOAT | Floating-point number, transferred as an INTEGER. This means that it will not be transferred in the floating-point format, but as an INTEGER – value coded according to the IEEE-754 standard. | 3242721280 (corresponds to -12.5) |
| DISCRETE | Discrete values, do not use " in the text, similar to Menu selection | mbar |
| BOOLEAN | Boolean values: ON or OFF (similar to DISCRETE) | ON |
| STRING | Character string | "ABCDE" |

Notes regarding control commands

- Cyclical commands Commands that last longer are processed cyclically. They will be automatically interrupted if a command occurs that requires an output.
- " (Inverted commas) A STRING is identified by inverted commas and a full-stop. These must be transferred with it (unlike DISCRETE).
- ' (apostrophe) An apostrophe is used, for example for emphasis. The apostrophe itself will not be transferred.
- () (brackets) Parameter inside round brackets are optional. The brackets themselves will not be transferred.
- , (comma) The comma is used to separate arguments. The next argument must follow immediately after the comma (no SPACE, ASCII-Code 32_{dez}).

3.8 Battery replacement

- Open the battery compartment and insert 3 x 1,5 V Mignon cell AA, IEC LR6.



Always replace all three batteries at the same time!
Ensure correct polarity!



Dispose of used batteries in accordance with environmental regulations!

3.9 Calibration


Re-calibration may only be carried out by specialist staff and with the corresponding pressure standards.

We recommend that you have the HM35 re-calibrated at least once a year, and, in case of highest demands for precision, several times a year.

Manual re-calibration


- In the **Menu**, select the **Calibration** → **Manual Calibration** function.

Zero point (Offset)

1. Open the pressure connection or, with the absolute pressure unit, set the given pressure value to the normal pressure.
2. Press the **Function** key ()
→ the zero point will be re-calibrated.

| CALIBRATION MAN. RECAL. | |
|-------------------------|--------|
| Reading | 0.3 |
| Set Press. | 0.0 |
| Set Press. | 7500.0 |
| mbar | |

Full-scale value

1. Set the given pressure value to the normal pressure.
2. Press the **Function** key ()
→ the full-scale value will be calibrated and the HM35 returns to normal operation.

| CALIBRATION MAN. RECAL. | |
|-------------------------|--------|
| Reading | 7001.3 |
| ✓ Set. Press. | 0.0 |
| Set. Press. | 7500.0 |
| | |
| mbar | |

Notes

- The calibration is always carried out in **mbar**.
- The calibration must take place at a stable room temperature of **22 °C ± 2 °C**.
- A calibration value will only be accepted if it lies **within ± 5 %** of the full-scale value of the HM35.
- With the pressure connections open, it is possible to only re-calibrate the zero point.
- The date of the last calibration will be stored in the **Calibration History**.
- In case of manual re-calibration, the previous measurement will become invalid. You should always carry out a complete accuracy check afterwards.

4 Specifications

4.1 Technical data

| | |
|--|--|
| Measuring media | Instrument air or inert gases |
| Media-compatibility | all media that is compatible with stainless steel 18/8 (DIN 1.4305) |
| Linearity, hysteresis and repeatability accuracy | according to measuring range and use See Table 4.2 |
| Units | according to measuring range and use See Table 4.3 |
| Operating temperature | 0 °C to 50 °C |
| Storage temperature | -20 °C to 60 °C |
| Humidity | max. 95 % rH. (non-condensing) |
| Case protection | IP 54 |
| Power supply | <ul style="list-style-type: none"> • 3 x 1,5 V Mignon-cell AA, IEC LR6 or accumulator • regulated 6 VDC plug-in mains supply unit (min. 6, max. 9 VDC) |
| Current consumption | < 25 mA without display light, IR and beeper |
| Battery life | approx. 90 hours |
| Infra-red interface | serial IR-protocol |
| Measuring rate | max. 25 measurements/s (Data logging, IR) 5 measurements/s (normal operation) |
| Display rate | 2 measurements/s |

| | |
|----------------------------|--|
| Memory size | max. 10'742 measurements |
| Memory interval | manual, 10, 25 measurements/s 1, 2, 5, 10, 30 s 1, 2, 5, 10, 30 min 1, 3, 6, 12, 24 h user-defined (user) |
| Average period | 10, 30 s 1, 2, 5, 10, 30 min 1, 3, 6, 12, 24 h user defined (user) |
| Display | LCD graphic display 128 x 64 points Background lighting |
| Pneumatic connection | 4/6 mm hose (M8 x 0,5) or NPT 1/8" Plug in nipple „Rectus“ Type 20 M10 x 1 inner thread (for connector „Minimess“) |
| Case dimensions | 200 x 93/58 x 39/28 mm |
| Weight including batteries | approx. 300 g |

4.2 Measuring Range and Precision

The measured values display works in the range from -10 % to 110 % of the measurement range.

| Measuring range | Unit | Pressure type | Resolution | Max. Loading | Max. static pressure |
|-----------------|--------------------|---------------|------------|-------------------------|----------------------|
| | | 1) | | | |
| 0 ... 10 | inH ₂ O | d,g | 0.0001 | 50 inH ₂ O | 245 psi |
| 0 ... 28 | inH ₂ O | d,g | 0.001 | 140 inH ₂ O | 245 psi |
| 0 ... 80 | inH ₂ O | d,g | 0.001 | 600 inH ₂ O | 245 psi |
| 0 ... 120 | inH ₂ O | d,g | 0.001 | 600 inH ₂ O | 245 psi |
| 0 ... 200 | inH ₂ O | d,g | 0.001 | 1600 inH ₂ O | 245 psi |
| 0 ... 14.5 | psi | d,g | 0.0001 | 58 psi | 245 psi |
| 0 ... 15.9 | psi | a | 0.0001 | 58 psi | -- |
| 0 ... 29 | psi | a,d,g | 0.001 | 100 psi | 245 psi |
| 0 ... 100 | psi | a,d,g | 0.001 | 245 psi | 245 psi |
| 0 ... 145 | psi | d,g | 0.001 | 390 psi | 390 psi |
| 0 ... 245 | psi | d,g | 0.01 | 390 psi | 390 psi |
| 0 ... 500 | psi | g | 0.01 | 1000 psi | -- |
| 0 ... 1000 | psi | g | 0.01 | 2000 psi | -- |
| 0 ... 1300 | psi | g | 0.01 | 2000 psi | -- |

| Measuring range | Unit | Accuracy | | | |
|-----------------|--------------------|------------------|--------|---------------------|--------|
| | | Inert gases | | Media compatibility | |
| | | % FS | % Rdg. | % FS | % Rdg. |
| | | | 2) | | 2) |
| 0 ... 10 | inH ₂ O | 0.1 / 0.2 | -- | -- | -- |
| 0 ... 28 | inH ₂ O | 0.05 / 0.1 / 0.2 | 0.1 | -- | -- |
| 0 ... 80 | inH ₂ O | 0.1 / 0.2 | -- | -- | -- |
| 0 ... 120 | inH ₂ O | 0.05 / 0.1 / 0.2 | 0.1 | -- | -- |
| 0 ... 200 | inH ₂ O | 0.1 / 0.2 | -- | -- | -- |
| 0 ... 14.5 | psi | 0.05 / 0.1 / 0.2 | 0.1 | 0.1 / 0.2 | -- |
| 0 ... 15.9 | psi | 0.1 / 0.2 | -- | -- | -- |
| 0 ... 29 | psi | 0.05 / 0.1 / 0.2 | 0.1 | 0.1 / 0.2 | -- |
| 0 ... 100 | psi | 0.05 / 0.1 / 0.2 | 0.1 | 0.1 / 0.2 | -- |
| 0 ... 145 | psi | 0.1 / 0.2 | -- | 0.1 / 0.2 | -- |
| 0 ... 245 | psi | 0.05 / 0.1 / 0.2 | 0.1 | 0.1 / 0.2 | -- |
| 0 ... 500 | psi | -- | -- | 0.1 / 0.2 | 0.1 |
| 0 ... 1000 | psi | -- | -- | 0.1 / 0.2 | 0.1 |
| 0 ... 1300 | psi | -- | -- | 0.1 / 0.2 | 0.1 |

- 1) a = absolute pressure
d = differential pressure
g = relative pressure

- 2) 0.1 % Rdg., but not less than 0.03 %FS.

4.3 Measurement units

The following units of measurement can be selected depending on the measuring range:

| Measurement ranges | mbar | bar | Pa | hPa | kPa | MPa | kg/cm ² | kg/m ² | mm Hg | cm Hg | mm Hg |
|--------------------|--------------------|-----|----|-----|-----|-----|--------------------|-------------------|-------|-------|-------|
| | | | | | | | 1) | 1) | 1) 2) | 1) 2) | 1) 2) |
| 0 ... 10 | inH ₂ O | • | -- | • | • | • | -- | -- | • | • | • |
| 0 ... 28 | inH ₂ O | • | -- | • | • | • | -- | -- | • | • | • |
| 0 ... 80 | inH ₂ O | • | • | • | • | • | -- | • | • | • | • |
| 0 ... 120 | inH ₂ O | • | • | • | • | • | -- | • | • | • | • |
| 0 ... 200 | inH ₂ O | • | • | • | • | • | -- | • | • | • | • |
| 0 ... 14.5 | psi | • | • | • | • | • | -- | • | • | • | • |
| 0 ... 15.9 | psi | • | • | • | • | • | -- | • | • | • | • |
| 0 ... 29 | psi | • | • | • | • | • | -- | • | • | • | • |
| 0 ... 100 | psi | • | • | • | • | • | -- | • | • | • | • |
| 0 ... 145 | psi | • | • | -- | • | • | • | • | • | • | • |
| 0 ... 245 | psi | • | • | -- | • | • | • | • | • | • | • |
| 0 ... 500 | psi | • | • | -- | • | • | • | • | • | • | • |
| 0 ... 1000 | psi | • | • | -- | • | • | • | • | • | • | • |
| 0 ... 1300 | psi | • | • | -- | • | • | • | -- | • | • | • |

| Measurement ranges | in Hg | mm H ₂ O | cm H ₂ O | m H ₂ O | in H ₂ O | ft H ₂ O | psi | lb/in ² (psi) | lb/ft ² | torr (mmHg) | atm |
|--------------------|--------------------|---------------------|---------------------|--------------------|---------------------|---------------------|-----|--------------------------|--------------------|-------------|-----|
| | 1) 2) | 1) 3) | 1) 3) | 1) 3) | 1) 3) | 1) 3) | 1) | 1) | 1) | 1) | 1) |
| 0 ... 10 | inH ₂ O | • | • | • | • | • | • | • | • | • | -- |
| 0 ... 28 | inH ₂ O | • | • | • | • | • | • | • | • | • | -- |
| 0 ... 80 | inH ₂ O | • | • | • | • | • | • | • | • | • | • |
| 0 ... 120 | inH ₂ O | • | • | • | • | • | • | • | • | • | • |
| 0 ... 200 | inH ₂ O | • | • | • | • | • | • | • | • | • | • |
| 0 ... 14.5 | psi | • | • | • | • | • | • | • | • | • | • |
| 0 ... 15.9 | psi | • | • | • | • | • | • | • | • | • | • |
| 0 ... 29 | psi | • | • | • | • | • | • | • | • | • | • |
| 0 ... 100 | psi | • | • | • | • | • | • | • | • | • | • |
| 0 ... 145 | psi | • | • | • | • | • | • | • | • | • | • |
| 0 ... 245 | psi | • | • | • | • | • | • | • | • | • | • |
| 0 ... 500 | psi | • | • | • | • | • | • | • | • | • | • |
| 0 ... 1000 | psi | • | • | • | • | • | • | • | • | • | • |
| 0 ... 1300 | psi | • | -- | • | • | • | • | • | • | • | • |

1) In relation to the acceleration due to gravity of 9,81 m/s²

2) at 0 °C 3) at 4 °C

Conversion factors

| | | | |
|-------------------|--------------------|--------------------|------------------------------|
| 1 mbar = 0,0010 | bar | 1 mbar = 10,1974 | mmH ₂ O (at 4 °C) |
| 1 mbar = 100 | Pa | 1 mbar = 1,01974 | cmH ₂ O (at 4 °C) |
| 1 mbar = 1,0 | hPa | 1 mbar = 0,0101974 | mH ₂ O (at 4 °C) |
| 1 mbar = 0,1 | kPa | 1 mbar = 0,40147 | inH ₂ O (at 4 °C) |
| 1 mbar = 0,00010 | Mpa | 1 mbar = 0,033456 | ftH ₂ O (at 4 °C) |
| 1 mbar = 0,00102 | kg/cm ² | 1 mbar = 0,01450 | psi |
| 1 mbar = 10,20 | kg/m ² | 1 mbar = 0,01450 | lb/in ² |
| 1 mbar = 0,75006 | mmHg (at 0 °C) | 1 mbar = 2,08854 | lb/ft ² |
| 1 mbar = 0,075006 | cmHg (at 0 °C) | 1 mbar = 0,75006 | torr |
| 1 mbar = 0,00075 | mHg (at 0 °C) | 1 mbar = 0,00099 | atm |
| 1 mbar = 0,02953 | inHg (at 0 °C) | | |

4.4 Mains supply unit connection

The unit can be operated from a regulated plug-in mains supply unit.

Input 100 - 240 V, 50 - 60 Hz
Output 6 VDC \pm 10 %, 1,5 W

5 Maintenance and storage

The HM35 requires no maintenance. It can be cleaned with a damp cloth. Do not use cleaning agents containing solvents!

See the relevant chapters for **battery replacement** und **re-calibration**.

During longer storage, remove the batteries from the instrument.

Do not drop below or exceed the admissible storage temperatures of -20 °C to 60 °C!

6 Warning messages and faults

| Code | Fault / Display | Possible cause | Correction |
|------|---------------------------------|---|---|
| | Does not switch on | Power supply missing | Possibly replace the batteries. Battery possibly inserted incorrectly. Possibly plug in power supply correctly. |
| | Instrument inaccurate | <ul style="list-style-type: none">• Re-calibration carried out inaccurately• Not zeroed• Natural aging of the pressure sensor | <ul style="list-style-type: none">• Re-calibrate• Vent and press Zero• Have it re-calibrated |
| | No change of the measured value | Excess pressure on sensor | Send instrument to the manufacturer for repair. |
| 14 | PRESSURE OUT OF RANGE! | Measurement range has been exceeded by more than 10 %. | Set up the permissible measurement pressure. |
| 13 | PRESSURE OUT OF RANGE! | <ul style="list-style-type: none">• Excess pressure on sensor• Electrical fault | Send instrument to the manufacturer for repair. |
| 06 | TEMPERATURE OUT OF RANGE! | Pressure sensor exposed to temperature outside permissible range (< -5 °C or > 55 °C) | Observe permissible operating temperature and temperature of the medium. |
| 04 | TEMPERATURE OUT OF RANGE! | Used outside permissible temperature range | Observe permissible operating temperature. |
| 15 | REF. VOLTAGE FAILURE! | Internal reference voltage error | Send instrument to the manufacturer for repair. |
| 07 | NOT CALIBRATED! | Incorrect calibration of the instrument | Send instrument to the manufacturer for repair. |
| 05 | LOW BATTERY! | Battery voltage too low | Replace batteries |
| | No IR communication | <ul style="list-style-type: none">• Line-of-sight connection interrupted• Separation too large• PC-configuration | <ul style="list-style-type: none">• Re-establish line-of-sight connection• Max. distance 50 cm• Check IR connection |

7 Accessories

- Standard 3 x 1,5 V batteries IEC LR6
 Operating instructions
 SCS Test certificate
- Options 6V mains supply unit 100 - 240 V, 50 - 60 Hz, 1,15 A
 Leather case with carrying strap
 Service-Set (transport case)
 Hand pump
 Infrared RS232 serial adapter
 NPT 1/8" adapter
 „Rectus“ adapter, type 20
 Communication software for MS-Windows® (95/98, 2000, XP)

8 Summary of technical characteristics

| Characteristics | HM35 | Remarks |
|--|--------|-----------------------------------|
| Basic functions | | |
| 1 pressure sensor installed | • | |
| Absolute pressure | • | |
| Differential pressure | • | |
| Relative pressure | • | |
| Vacuum (relative under-pressure) | • | The instrument is only calibrated |
| for inert gases | • | in the over-pressure range |
| Media compatibility rel./abs. | • | |
| Measuring ranges / Accuracy | | |
| Calibrated temperature range 0 ... 50 °C | • | See separate table |
| Measuring functions | | |
| Pressure / Differential pressure | • | |
| Min/Max | • | |
| Average | • | Average per time period |
| Change Rate | • | Tendency / leak rate |
| Other functions | | |
| Set-up/Configuration | | |
| Unit switchable | • | |
| Display filter | • | |
| Auto-off | • | |
| Record interval | • | Free choice |
| Average period | • | Free choice |
| Display rate | 2 M/s | |
| Max. measurement rate | 25 M/s | Approx.. |
| Date / Time (real time) | • | |
| Analogue bar display | • | |
| Real time data logging | • | |
| Data logging / manual record | • | |
| Print record | • | |
| Number of records | 10742 | Max. |
| Zeros with key | • | |
| Automatic zeroing | • | |
| Hold | • | |
| Display accuracy at start-up | • | |

| Characteristics | HM35 | Remarks |
|------------------------------------|------|--|
| Low battery display | • | |
| Acoustic signal | • | For out-of-range / fault operation |
| Self-test | • | |
| | | |
| Housing | | |
| Hand-held | • | |
| Splash proof IP54 | • | |
| | | |
| Connections | | |
| Tube 4/6 mm | • | M8 x 0,5 |
| NPT1/8" internal | • | |
| Plug-in nipple „Rectus“ Type 20 | • | |
| M10 x 1 internal thread | • | For „Mininess“ 1215 |
| Power supply socket | • | |
| | | |
| Display | | |
| Graphic display | • | |
| Lighting | • | Reduced brightness in Ex-version |
| Automatic contrast adjustment | • | for temperature changes |
| | | |
| Power supply | | |
| Battery | • | |
| External plug-mounted power module | • | |
| | | |
| Digital interfaces | | |
| Infrared interface | • | |
| SCPI protocol | • | Standard Commands for Programmable Instruments |
| | | |
| Environmental conditions | | |
| Operating temperature 0 ... 50 °C | • | |
| Storage temperature -20 ... 60 °C | • | |
| Humidity max. 95 %r.F. | • | Non-condensing |

Trademark Windows is property of Microsoft Corporation.

**LOVE CONTROLS Division
Dwyer Instruments, Inc.
102 Indiana Highway 212
Michigan City, IN 46360
USA
Phone ++1 219 879 8868
Fax ++1 219 872 9057**