Handbook

© KROHNE 03 / 2005

FH & JZ



IFC 300 signal converter

for electromagnetic flowmeters

KROHNE

for volumetric flow measurement of electrically conductive liquids



OPTIFLUX flowmeters are delivered ready for operation! Switch on and measure.

Software Version 1.1.0

Subject to change without notice.

Variable area flowmeters
Vortex flowmeters
Flow controllers
Electromagnetic flowmeters
Ultrasonic flowmeters
Mass flowmeters
Level measuring instruments
Communications technology
Engineering systems & solutions
Switches, counters, displays and recorders
Heat metering
Pressure and temperature

	Contents	
•	CE / EMC / Standards / Approvals	3
•	Safety information	4
•	System description	4
•	Product liability and warranty	4
•	Items included with supply	5
•	Signal converter versions and device nameplates	5
1	Electrical connection: power supply	6 - 15
1.1	Location and important notes on installation PLEASE NOTE !	6 - 7
1.2	Connection to power for IFC 300 versions C, F and W	8
1.3	Electrical connection of remote sensors (primary heads)	9 - 15
1.3.1	General information on signal cables A and B, and field current cable C	9
1.3.2	Stripping (preparation) of signal cables A and B	10
1.3.3	Type, length and preparation of field current cable C	11
1.3.4	Grounding of sensors (primary heads)	12
1.3.5	Length of signal cable	
	max. distance between signal converter and sensor (primary head)	13
1.3.6	Connection diagrams (I and II) for power supply and sensors	14 - 15
2	Electrical connection: outputs and inputs	16 - 28
2.1	Important information on outputs and inputs PLEASE NOTE !	16
2.2	I / O assemblies	16-18
2.3	Current output	19
2.4	Pulse and frequency output	20
2.5	Status output and limit switches	21
2.6	Control input	22 - 23
2.7	Connection diagrams (1 - 17) for inputs and outputs	24 - 28
3	Start-up	29

4	Operator control of the signal converter	30 - 51
4.1	Display, operating and control elements	30
4.2	Function of the keys	31
4.3	KROHNE program structure for EMFs	32
4.4	Tables of settable functions	33 - 43
4.5	To reset counters	44
4.6	To delete error messages	44
4.7	General directions for special measurements, tasks and diagnostics	45
4.8	Special measurements	46
4.9	Special measurement tasks and diagnostics	46 - 47
4.10	Status messages and diagnostic information	48 - 51
5	Technical data	52 - 59
5.1	IFC 300 signal converter	52 - 55
5.2	Selection table for KROHNE sensors (primary heads)	56
5.3	Flow table	56
5.4	Measuring accuracy / error limits	57
5.5	Dimensions and weights	58
•	If you need to return flowmeters to KROHNE for testing or repair	59
•	Form to accompany a returned device (can be copied)	59

CE / EMC / Standards / Approvals

CE

The electromagnetic flowmeters from KROHNE described in this handbook meet the following safety requirements:

- EMC Directive 89 / 336 / EEC and 93 / 68 / EEC in conjunction with EN 61326-1 (1997) and A1 (1998), A2 (2001)
- Low-Voltage Directives 73 / 23 / EEC and 93 / 68 / EEC in conjunction with EN 61010-1: 2001
- Pressure Equipment Directive 97 / 23 / EC
- Ex Directive 94 / 9 / EC (ATEX 100a) for versions designed for use in hazardous areas
- All devices bear the CE marking and meet the requirements of
- NAMUR Guideline NE 21 / 04 with IFC 300 signal converter.

Safety information

Please read these operating instructions and observe applicable national standards, safety requirements and accident prevention regulations.

Installation and operation of the measuring device may only be carried out by qualified personnel.

	Warning sign: electric shock hazard	WARNING! Electric shock is dangerous and can cause severe burns and critical injuries!
<u>(</u> ٤x	Separate manuals available for hazardous- duty equipment!	CAUTION! Special regulations apply to use of equipment in hazardous areas, and these must be observed without fail in order to ensure safe operation in such areas. Wiring, installation, operation and maintenance may only be carried out by qualified personnel trained in explosion protection.
	WARNING! CAUTION!	WARNING! Indicates activities or occurrences which, if ignored, can lead to serious personal injury, hazardous situations, faulty operation or destruction of the device. CAUTION! Indicates activities or occurrences which, if ignored, can lead to personal injury and faulty operation of the device.
i	Info	Information and tips

System description

Electromagnetic flowmeters are precision instruments designed for linear flow measurement of liquid products.

The process liquids must be electrically conductive, \geq 1 $\mu S/cm$ (depending on the sensor); for cold demineralized water: \geq 20 $\mu S/cm.$

The full-scale range $Q_{100\%}$ can be set as a function of the sensor meter size (primary head) in keeping with the flow velocity between v = 0.3 – 12 m/s, see flow table in Sect. 5.3.

Product liability and warranty

Electromagnetic flowmeters from KROHNE are designed solely for measuring the flow rate and the conductivity of electrically conductive process liquids.

Such flowmeters are also available for use in hazardous areas. Special regulations apply in this case, which are given in the special EEx directions, see separate operating instructions.

Responsibility as to suitability and intended use of these electromagnetic flowmeters rests solely with the operator.

Improper installation and operation of the flowmeters (systems) may lead to loss of warranty.

In addition, the "General conditions of sale" forming the basis of the purchase contract are applicable.

If flowmeters need to be returned to KROHNE, please note the information given on the last-but-one page of these Instructions. KROHNE regret that they cannot repair or check your flowmeter(s) unless they are accompanied by the completed form sheet.

Items included with supply

- Signal converter in the version as ordered.
- Signal cable (only for remote versions F and W) in the version and length as ordered (Standard: signal cable A, length 5 m)
- Report on factory settings
- Calibration report
- Quick Start directions, in the language ordered, for installation, electrical connection, start-up and operator control of the signal converter.
- CD-ROM with manuals for the sensors and the signal converter.

Signal converter versions and device nameplates

Your measuring device is delivered in ready-to-operate condition. Operating data have been factory-set to your order. The signal converter is equipped as standard with a local display, operator control elements and with a **HART**[®] interface

 IFC 300 C
 Compact flowmeter, signal converter mounted directly on the flow sensor

 IFC 300 F
 Signal converter in field housing, remote version, electrical connection to the flow sensor via field current and signal cables

 IFC 300 W
 Signal converter in wall-mounted housing, remote version, electrical connection to the flow sensor via field current and signal cables

- IFC 300 R Signal converter in 19" rack, remote version, electrical connection to the flow sensor via field current and signal cables (in preparation)
- C and F (option) These versions available for use in hazardous areas.

Please check against the **device nameplates** that the device supplied is in the correct version, see following examples. The nameplate for inputs/outputs is illustrated in Sect. 2.2.

WRCOHENE 3313 LC, Dordrecht, The Netherlands OPTIFLUX 1300 C A04 12345 Manufactured 2004 GK = 2,1234 K50 = 1,1234 DNS0 PN401 field = f line / 2 100 - 230 VAC, -15% / + 10% Sold Vetted materials: PFA, HC IP67 Nema type 4X, 6 enclosure T m,max = 180 °C p max.20 = 16 bar Tag: Pilot series, field test FT54NL	II 2GD EEx dqe [ia] IIC 16 T3 KEMA 04 ATEX 2200 X T amb = -40 °C +65 °C See manual for maximum medium temperatures After de-energizing delay before opening the converter housing: 16 > 35 min., T5 > 10 min. Coil Housing factory sealed, do not open Um = 253 V Non-EEx i circuits A, B, C, D: Un < 35 V; In < 100 mA Accuracy class 0.5; MMQ = 200 liter Qmin = 2 m3/h; Qmax = 50 m3/h Visc. 1 mPa.s - 10 mPa.s P min = 1 bar; p max = 180 °C	$\begin{tabular}{ c c c c c } \hline \end{tabular} Barbon Barb$
GK = 2,1234 GKL = 5,1234 K50 = 1,1234 K2 DN50 PN40 f field = f line / 2 IP67 Nema type 4X,6 enclosure p max,2	CXX KEMA 04 ATEX 2200 X No 6 0344 T amb = -40 °C +65 °C See manual for maximum medium temperatures Coil bousing factory sealed do not open Coil bousing factory sealed do not open	Accuracy class 0.5; MMQ = 200 liter Qmin = 2 m3/h; Qmax = 50 m3/h Visc. 1 mPa.s - 10 mPa.s P min = 1 bar; p max = 100 bar Tmin=-20 °C; Tmax = 180 °C Tag: Pilot series, field test FT54NL

Examples for nameplates

1 Electrical connection: Power supply

1.1 Location and important notes on installation

PLEASE NOTE !


- Electrical connection in conformity with VDE 0100 "Regulations for electrical power installations with line voltages up to 1000 V" or equivalent national regulations.
- Use separate entry fittings (PG screwed cable entries) for power supply, field current and signal cables, and for outputs and inputs.
- Protect signal converter against direct **solar radiation**, install a sunshade if necessary.
- Signal converters installed in switchgear cabinets require adequate cooling, e.g. by fan or heat exchanger.
- Do not expose signal converters to intense vibration. KROHNE OPTIFLUX are tested at vibrational level to IEC 68-2-34: broadband vibration test: f₁ = 20 Hz / f₂ = 2000 Hz / t = 90 min. / Test in all three axes (directions), spectral acceleration density ASD = 0.01 g² / Hz (a_{eff.} = 4.5 g).
- Dimensions of the signal converter, see Sect. 5.5.

For separate systems / remote signal converters only (F and W versions)

- Mounting of the remote signal converter
- Mounting of the IFC 300 W: Remove mounting plate from rear of signal converter, and attach to wall or standpipe. Replace signal converter. Position lock washers and nuts on the housing bolts, tighten nuts slightly. Align housing, tighten nuts firmly.
 Dimensions, further information (minimum distances between signal converters): see Sect. 5.5, Dimensions and weights
- Mounting the IFC 300 F: Mount IFC 300 F with mounting plate on wall or standpipe.
 Dimensions, further information (minimum distances between signal converters): see Sect. 5.5, Dimensions and weights
- Keep distance between flow sensor and signal converter as short as possible, observe max. allowed length of signal and field current cables, see Sect. 1.3.3 and 1.3.5.
- Use the supplied **KROHNE signal cable A** (type DS 300, standard) **or B** (type BTS 300, bootstrap, optional), standard length 5 m / 15 ft.
- Generally use bootstrap signal cables B (type BTS 300) for OPTIFLUX 5000 F and OPTIFLUX 6000 F flow sensors, meter sizes DN 2.5 15 and ¹/₁₀" ¹/₂", and for contaminated liquids which tend to form electrically insulating deposits.
- Always calibrate flow sensor and signal converter together! Also install together and make sure settings of the primary constant GK / GKL are identical, see device nameplates and report on settings for the signal converter.

If components are supplied separately, or in the case of a "mixed" installation, the signal converter must be set to the DN size and GK / GKL of the sensor; see Sect. 4.

Construction of the various housing versions



The terminal compartments are accessible after unscrewing cover 2 (and 5, for F Version only).

- 1 Cover, electronics compartment
- 2 Cover, terminal compartment for power supply and inputs/outputs
- 3 Cable entry for power
- 4 Cable entry for inputs/outputs


for F Version only (remote)

- 5 Cover, sensor terminal compartment
- 6 Cable entry for field current cable
- 7 Cable entry for signal cable
- 8 Attachment plate for wall or pipe mounting
- 9 Locking screw for cover of sensor terminal compartment(5)

The display of the IFC 300 C and IFC 300 F can be turned in steps of 90°.

To do this, unscrew the cover of the electronics compartment and remove the two metal clips to the left and right of the display using a screwdriver or similar tool. The display between the metal clips can then be pulled off and re-inserted in the required position. Before pushing the clips together with the display into the electronics compartment, make sure not to kink the display's flat ribbon cable more than absolutely necessary. Replace cover and tighten down by hand.

Cover threads to be protected from dirt and well greased at all times; particularly important for hazardous-duty (Ex) versions!



IFC 300 W (remote)

- 1 Cover, electronics compartment
- 2 Cover for the three separate terminal compartments for power, sensor connection and inputs/outputs
- **3** Locking screw, ¹/₂ turn left/right to open/close cover (**2**)
- 4 Safety lever to open cover (1)
- **5** Sensor terminal compartment, open separate cover
- 6 Terminal compartment, outputs/inputs
- 7 Power terminal compartment, open separate shock-hazard protection cover
- 8 Entry fitting for signal cable
- 9 Entry fitting for field current cable
- 10 Two cable entries for outputs/inputs
- 11 Cable entry for power supply

1.2 Connection to power for IFC 300 versions C, F and W

PLEASE NOTE !

- <u>Degree of protection</u> IP 65 and 67 to IEC 529 / EN 60529, equivalent to NEMA 4 / 4X and 6, dependent on the version.
- <u>Rated values:</u> The housings of the flowmeters, which are designed to protect the electronic equipment from dust and moisture, should be kept well closed at all times. Creepage distances and clearances are dimensioned to VDE 0110 and IEC 664 for pollution severity 2. Supply circuits are designed for overvoltage category III and the output circuits for overvoltage category II.
- Fuse protection, disconnecting device: Fuse protection (I_N ≤ 16 A) for the infeed power circuit, and also a disconnecting device (switch, circuit breaker) to isolate the signal converter must be provided.


100-230 Volt AC (tolerance range -15% / +10%)

- Note the data on the nameplate, power supply voltage and frequency range (50 60 Hz).
- The **protective ground conductor PE** of the power supply **must be connected** to the separate terminal in the terminal compartment of the signal converter.
- **Connection diagrams I II** for the power supply and the electrical connection between flow sensor (primary head) and signal converter: see Sect. 1.3.6.

12 - 24 Volt DC (tolerance range -25% / +30%)

- Note the data on the instrument nameplate!
- For reasons to do with the measurement process, connect a **functional ground FE** to the separate U-clamp terminal in the terminal compartment of the signal converter.
- When connecting to functional extra-low voltages, provide a facility for protective separation (PELV) (VDE 0100 / VDE 0106 and/or IEC 364 / IEC 536 or relevant national regulations).
- **Connection diagrams I II** for the power supply and the electrical connection between flow sensor and signal converter: see Sect. 1.3.6.

Connection to power (applies to all versions / housing versions)



The power terminals in the terminal compartments are protected by additional hinged lids against accidental contact.

Warning: Signal converter must be properly grounded to avoid personnel shock hazard. All directions, operating data and connection diagrams do not apply to devices used in hazardous areas; in such cases, read the **special "Ex" operating** instructions without fail!


1.3 Electrical connection of remote sensors (primary heads)


1.3.1 General information on signal cables A and B and field current cable C

i	Proper functioning is ensured by the KROHNE signal cables A and B with double or triple foil shielding.								
	However, when other signal cables are used, please note the following electrical data!								
	Electrical safety to EN 60811	Test voltage							
	(low-voltage directives)	Signal wire / inner shield	500 V						
	or equivalent national standards.	Signal wire / signal wire	1000 V						
	Capacitance of signal wire	Signal wire / outer shield	1000 V						
	wire / wire < 50 pF/m or 15 pF/ft	Twisting of signal wires							
	wire / shield < 150 pF/m $\overline{\text{or}}$ 45 pF/ft	minimum 10× per meter or							
	Isolation resisance >100 G Ω × km or >60 G Ω × mil	e important when screening	magnetic fields						
	Voltage rating < 24 V / Current rating < 100 mA								

- Lay signal cables as a fixed installation, underwater and underground laying possible. Connection of shields:
 - inner (1) via drain wire to normal connecting terminal
 - outer (60) via braid to U-clamp terminal
- Insulating material is flame-retardant to EN 50625-2-1, IEC 60322-1.
- The low-halogen, unplasticized signal cables remain flexible at low temperatures.

Signal cable A (type DS 300), with double shielding





- 1.0 mm² Cu / AWG 17 (not insulated, bare)
- -10 Inner shield (see stranded drain wire 1)
 - -2 Insulated conductor, 0.5 mm² / AWG 20 (marking = 2)
- 20 Stranded drain wire for individual shield of conductor 2
- -3 Insulated conductor, 0.5 mm² / AWG 20 (marking = 3)
- 30 Stranded drain wire for individual shield of conductor 3
- 6 Stranded drain wire, outer shield,
 - 0.5 mm² Cu / AWG 20 (not insulated, bare)
- **60** Outer shield (see stranded drain wire 6)

Outer sheath, dia. approx. 12 mm / 0.5" (marking = BTS 300)

In the bootstrap method, the individual shields (20 and 30) are always controlled by the signal converter to exactly the same voltage that is present at signal wires (2 and 3). Because for that reason there is no voltage difference between the individual shields (20 and 30) and the signal wires (2 and 3), no current flows via the line capacitances between 2 / 20 or 3 / 30. The line capacitance is apparently "zero". This allows greater cable lengths when the electrical conductivity of the process product is low.

Field current cable C

Cross-section dependent on required length of cable, see Table in Sect. 1.3.3.

1.3.2 Stripping (preparation) of signal cables A and B

Please note:

- The **figures** in tables and drawings identify the shields, stranded drain wires and wires of signal cables A and B, see Sect. 1.3.1.
- The following tables and drawings indicate the dimensions (a d) for stripping the signal cables.

approx. Length in min / men							
dimen-	Sensor	Sensor Signal cor					
sion		IFC 300 F	IFC 300 W				
а	60 / 2.4"	90 / 3.5"	90 / 3.5"				
b	10 / 0.4" 10 / 0.4"	10 / 0.4"	10 / 0.4"				
С	8 / 0.3"	8 / 0.3"					
60	connect	connect	do not connect				

Signal cable A (Typ DS 300) approx. Length in mm / inch


Customer-supplied materials

W	Insulation tubing (PVC),
	Insulation tubing (PVC), dia. 2.0-2.5 mm / approx. 0.1"
Х	Heat-shrinkable tubing or cable sleeve
Y	Wire end ferrule to DIN 41 228: E 1.5-8
Z	Wire end ferrule to DIN 41 228: E 0.5-8


Signal cable B (Typ BTS 300) approx. Length in mm / inch

dimen-	Sensor	Signal converter					
sion		IFC 300 F	IFC 300 W				
а	60 / 2.4"	90 / 3.5"	90 / 3.5"				
b	10 / 0.4"	10 / 0.4"	10 / 0.4"				
С	8 / 0.3"	8 / 0.3"	8 / 0.3"				
d	-	25 / 1.0"	25 / 1.0"				
60	connect	connect	do not connect				
20 / 30	do not connect	connect only in the IFC 300					

Signal cable A (type DS 300), with double shielding



Signal cable B (type BTS 300), with triple shielding (bootstrap)



1.3.3 Type, length and preparation of the field current cable C

Length and c	ross-section,	field	current	cable C	
--------------	---------------	-------	---------	---------	--

Length		Cross-section A _F (Cu)
0 – 150 m	0 - 500 ft	3 x 0.75 mm² Cu 3 x AWG 18
150 – 300 m	500 - 1000 ft	3 x 1.50 mm² Cu 3 x AWG 14
300 – 600 m	1000 - 2000 ft	3 x 2.50 mm² Cu 3 x AWG 12


Cu = copper cross-section

For the IFC 300 W the terminals are designed for the following cable cross-sections:

• flexible cable: $\leq 1.5 \text{ mm}^2 / \leq AWG 14$

• solid cable: $\leq 2.5~mm^2\,/ \leq AWG~12$

Preparation



1.3.4 Grounding of sensors (primary heads)

- The sensor must be properly connected to ground.
- The grounding cable should not transmit any interference voltages.
- Do not use the grounding cable to connect more than one device to ground.
- In hazardous areas, grounding is used at the same time for equipotential bonding. Special grounding instructions are contained in the "Ex-installation instructions", which are only supplied together with hazardous-duty equipment.
- The sensors are connected to ground by means of a functional grounding conductor FE.
- Special grounding instructions for the various sensors are contained in the separate installation instructions for the sensors.
- These instructions also contain detailed descriptions on how to use grounding rings and how to install the sensors (primary heads) in metal or plastic pipes or in pipes which are coated on the inside.



Warning: The signal converter must be properly grounded to avoid personnel shock hazard. All diections, operating data and connection diagrams do not apply to devices used in hazardous areas; in such cases, read the special "Ex" operating instructions without fail.

1.3.5 Length of signal cable


max. distance between signal converter and sensor (primary head)

Abbreviations and explanatory notes

for the following table, diagram and connection diagrams

- A Signal cable A / type DS 300, double shielding, max. length: see diagram below
- B Signal cable B / type BTS 300, triple shielding, max. length: see diagram below
- C Field current cable, cross-section and length: see Sect. 1.3.3
- σ Electrical conductivity of process liquid

Sensor			Mete	r size			Min. elec	Curve for	signal cable
primary head							conductivity	Α	
	DI	۱m	nm	i	nche	es	μS / cm		DN mm
OPTIFLUX 1000 F	10	-	150	³ / ₈	-	6	5	A 1	B 2
OPTIFLUX 2000 F	25	-	150	1	-	6	20	A 1	В 3
	200	-	2000	8	-	80	20	A 2	B 4
OPTIFLUX 4000 F	2.5	-	6	¹ / ₁₀	-	¹ / ₆	10	-	B 1
	10		150	³ / ₈	-	6	1	A 1	B 3
	200	-	2000	8	-	80	1	A 2	B 4
OPTIFLUX 5000 F	2.5			¹ / ₁₀			10	-	B 1
	4	-	15	¹ / ₆	-	¹ / ₂	5	-	B 2
	25	-	100	1	-	4	1	A 1	B 3
	150	-	250	6	-	10	1	A 2	B 4
OPTIFLUX 6000 F	2.5	-	15	¹ / ₁₀	-	¹ / ₂	10	-	B 1
	25	-	150	1	-	6	1	A 1	В 3



1.3.6 Connection diagrams (I and II) for power supply and sensors

Important notes for connection diagrams PLEASE NOTE !




Warning: Signal converter must be properly grounded to avoid personnel shock hazard. All directions, operating data and connection diagrams do not apply to devices used in hazardous areas; in such cases, read the special "Ex" operating instructions without fail!

- The figures in brackets identify the shields, stranded drain wires and cores of signal cables A + B, see sectional drawings of signal cables in Sect. 1.3.1.
- Electrical connection to VDE 0100 "Regulations governing heavy-current installations with line voltages up to 1000 V"
- Power supply 12 24 V DC:

Functional extra-low voltage with safety separation (PELV) to VDE 0100/VDE 0106 and/or IEC 364/IEC 365, or equivalent national regulations.

- Systems used in hazardous areas are subject to special regulations concerning electrical connections (see separate manual).
- **Terminal 4 / 40:** assigned only when sensors have 4 electrodes (special version)
- **PE** = protective conductor **FE** = functional ground




For IFC 300 F !

- IFC 300 F has separate terminal compartments for power supply, flow sensor and for outputs and inputs.
- Connect the two overall shields for signal cables A and B in the sensor outlet box **and** in the signal converter-sensor terminal compartment: inner shield (10) by way of the stranded drain wire (1), and outer shield (60) by way of the braid.
- There should be no difference in potential between the sensor and the housing of the signal converter!

For IFC 300 W !

- IFC 300 W has 1 cover for the separate terminal compartments for power supply, sensor and for outputs and inputs. The power terminal compartment has an additional hinged flap for shock-hazard protection.
- The outer overall shield (60) of signal cables A and B can only be connected up in the sensor outlet box!



Sensor / primary head

2 Electrical connection: outputs and inputs

2.1 Important information for outputs and inputs


- The output / input groups are galvanically separated from each other and from all other input and output circuits.
- Active mode: The signal converter supplies the power for operation (activation) of receiver instruments; observe max. operating data.
- **Passive mode:** Operation (activation) of receiver instruments requires an external power supply (U_{ext}); observe max. operating data.
- Connection diagrams of outputs and inputs are shown in Sect. 2.7.
- For operating data of outputs and inputs, refer to Sect. 2.7 and 5.1.

2.2 I / O assemblies for the outputs and inputs

IFC 300 is available with a choiceof output/input assemblies:

- The **Basic I/O** has one mA, one pulse and 2 status outputs. The pulse output can be set as a status output, and one of the status outputs as a control input (see **Basic I/O table**).
- The Modular I/O can be equipped with different output modules, depending on the task (see Modular I/O table).
- For hazardous areas, all I/O variants are available for the IFC 300 C (compact) and IFC 300 F (remote) with terminal compartment in EEx - d (flameproof enclosure) or EEx - e (increased safety) protection.
- The **Bus System I/O** allows intrinsically safe and non-intrinsically safe bus interfaces in combination with further modules (see **Bus System I/O** table).
- The last 3 places of the CG No. indicate the assigned terminals, see examples below.
- Abbreviations used are explained in the small table on the next but one page.

Examples of CG No. to identify the electronic module and the I/O variants:



CG No. (examples)

CG 300 11 100	100-230 V AC & Standard Display / Basic I/O: I_a or $I_p \& S_p/C_p \& S_p \& P_p/S_p$ (see Tabele and Nameplate on the next page)
CG 300 11 7FK	100-230 V AC & Standard Display / Modular I/O: $I_a \& P_n/S_n$ and option module $P_N/S_N \& C_N$ (see Tables on the next but one page)
CG 300 81 4EB	24 V DC & Standard Display / Modular I/O: $I_a \& P_a/S_a$ and option module $P_p/S_p \& I_p$ (see Tables on the next but one page)

PLEASE NOTE !

		Terminals								
I/Os	CG-No.	D-	D	C-	С	B-	В	A-	Α	A+
Basic 1 0 0 Standard		-	P _p / S _p (changeable)		Sp		S _p / C _p (changeable)		Ip + HART® or (reverse term.)	
EEx - i Option	2 0 0		PN / SN NAMUR (changeable) Ia + HART [®] active		RT [®] active				<	\mathbb{N}
	3 0 0		NAMUR ngeable)	I _p + HAR	T[®] passive			\land	<	\mathbf{X}
	2 1 0		P _N / S _N NAMUR (changeable) I _a + HART [®] activ		RT [®] active	P _N / S _N / C (chang		I,	a	$\left \right>$
	3 1 0	P _N / S _N NAMUR (changeable)		I _p + HART [®] passive		P _N / S _N / C _N NAMUR (changeable)		I,	a	$\left \right>$
	2 2 0 P _N / S _N NAMUR (changeable)		I _a + HART [®] active		P _N / S _N / C _N NAMUR (changeable)		I,	р	\mid	
	3 2 0		NAMUR ngeable)	I _p + HART [®] passive		P _N / S _N / C _N NAMUR (changeable)		I	р	$\left \right>$
PA - Bus	D 0 0	Term PA-	Term PA+	Term PA-	Term PA+				/	Λ /
PROFIBU		-) Device	FISCO Device			<	\geq	<	\bigvee
(EEx-i) Option	D 1 0	Term PA- FISCO	Term PA+ Device	Term PA- FISCO	Term PA+ Device	P _N / S _N / 0 (chang		I,	a	\times
D 2 0 Term PA- FISCO		Term PA+ Device	Term PA- FISCO	Term PA+ Device	P _N / S _N / C (chang		l	p	$\left \right>$	
FF - Bus <i>E</i> 0 0		Term V/D-	Terrm V/D+	Term V/D-	Terrm V/D+				/	\wedge /
Foundation			Device) Device	>	<	>	<	$\downarrow \searrow$
Field-Bus		Term V/D-	Terrm V/D+	Term V/D- Terrm V/D+ FISCO Device		P _N / S _N / 0 (chang		I,	a	\mathbf{X}
Option	E 2 0		Terrm V/D+ D Device	Term V/D- FISCO	Terrm V/D+ Device	P _N / S _N / C (chang		I,	p	$\left \right>$

Fixed, unalterable I/Os (input/output versions)

Nameplate inputs/outputs

Example of CG No., here: **BASIC I/O**

POWER) PE (FE) L(L+) N(L-)	CG30*_100 7.12345.XX.00
•		A = Active P = Passive NC = Not connected
	D - D	P ULSE OUT / STATUS OUT Imax = 100 mA@f<=10 Hz; = 20 mA@f<=12 kHz Uo = 1,5 V @ 10 mA; Umax = 32 VDC
DUTPUT	с. с	P STATUS OUT Imax = 100 mA; Umax = 32 VDC
INPUT / OUTPU	В- В	P STATUS OUT / CONTROL IN Imax = 100 mA Uon > 19 VDC; Uoff < 2,5 VDC; Umax = 32 VDC
	A + A - A	A CURRENT OUT (HART) P Active (Terminals A & A+); RL max = 1 k ohm A/P Passive (Terminals A & A-); Umax = 32 VDC

Alterable I/Os (input/output versions)

- The grey boxes denote freely selectable option modules for terminals A and B.
- Terminal A+ functions only for the Basic I/O.
- For hazardous areas, all I/O variants for IFC 300 C and IFC 300 F are available with terminal compartment in EEx d (flameproof enclosure) or EEx e (increased safety) protection.

		Terminals								
I/Os	CG-No.	D- D		C-	С	В-	В	Α-	Α	A+
Modular Option	4	-	/ S ₄ geable)	I _a + HAR1	[®] active		2 option m • A: I a or			\mid
	8	-	P_a / S_a (changeable) $I_p +$		[®] passive		2 option m • A: I _p or			\mid
	6	Ρ _p / S _p (changeable)				max. 2 option modules for term. B + A: I _a or P _p / S _p or C _p			for	$\left \right $
	B	P _p / S _p (changeable)		I _p + HART	® passve		2 option m • A: I p or			\mid
	7	P _N / S _N NAMUR (changeable)		Ia + HART	® active	max. 2 term. B +	2 option m • A: I a or			\mid
	c	P _N / S _N NAMUR (changeable)		I _p + HART	[®] passve	/e max. 2 option modules for term. B + A: I _p or P _N / S _N or			\mid	
PA - Bus PROFIBUS Option	D S	Term PA-	Term PA+	Term PA-	Term PA+		2 option m • A: I a or			\mid
FF - Bus Foundatio Option	E n Field-Bus	Term V/D-	Terrm Term Terrm V/D+ V/D- V/D+			2 option m • A: I a or			\mid	
DP - Bus PROFIBUS Option	F _ 0 S	RxD/TxD N	RxD/TxD P	RxD/TxD N	Termin. N	RxD/TxD P	Termin. P	max. 1 modu term see t below selec	le for . A: able w for	

Option modules

Abbreviation	Description	Ident for CG No.
la	Active current output	Α
lp	Passive current output	В
P _a / S _a	Active pulse, frequency, status output or limit switch	С
P _p / S _p	Passive pulse, frequency, status output or limit switch	
P _N / S _N	Pulse, frequency, status output or limit switch to NAMUR	F
Ca	Active control input	G
C _a C _p C _N	Passive control input	к
C _N	Control input to NAMUR	н
-	No module installed	8
-	No further module possible	0

2.3 Current output

i


Depending on the version, the outputs and inputs to be connected passively or actively and / or to NAMUR EN 60947-5-6! The tables in Sect. 2.2 show which I/O version and which inputs and outputs are installed in your signal converter, see also the sticker inside the cover of the terminal compartment.

- All current outputs are galvanically separated from each other and from all other circuits.
- Depending on the version, up to 3 current outputs in parallel can be built in, one always with HART[®] communication (except for Foundation Fieldbus and PROFIBUS).
- Factory-set data and functions are given in the enclosed report on settings.
- All operating data and functions are settable, see Sect. 4.4.
- **Passive mode** external power supply $U_{ext} \le 32 \text{ V DC}$ bei $I \le 22 \text{ mA}$
- Active mode load impedance $R_L \le 1 k\Omega$ at $I \le 22 mA$ (not applicable to EEx-i, see separate Ex – operating instructions)
- Self-monitoring interruption of mA loop or
 load impedance too high in mA loop
- Error message via status output (see Fct. C 2.x.01).
- Current value for error identification adjustable, see Fct. C 2.x.03 (current output).
- Range change, automatically by status output or manually by control input, see Sect. 4.4, Fct. C 2.x.11 and C 2.x.12 (for current output) and Fct. C 2.x.01 (for status output or control input).

Setting range threshold between 5 - 80% of $Q_{100\%}$, ± 0 - 5% hysteresis (appropriate ratio from low to high range of 1:20 to 1:1.25).

The active range is signalled via a status output.

- Forward / reverse flow measurement (F/R mode) is possible, see Fct. C 2.x.07 (current output) and Fct. C 2.x.01 (status output).
- Connection diagrams, see Sect. 2.7



2.4 Pulse and frequency output

i

Depending on the version, outputs and inputs to be connected passively or actively and/or to NAMUR EN 60947-5-6. The tables in Sect. 2.2 show which I/O version and which inputs and outputs are installed in your signal converter. See also the sticker inside the cover of the terminal compartment.

The pulse or frequency output can be set under Fct. C 2.1 Hardware.

- All **pulse / frequency outputs are galvanically separated** from all other circuits and from each other.
- Depending on the version, several pulse / frequency outputs can be installed in parallel.
- Factory-set data and functions will be found in the enclosed report on factory settings.
- All operating data and functions are adjustable, see Sect. 4.4.
- Passive mode requires external power source: $U_{ext} \leq 32 V$ DC $~U_o$ 1.5V @ 10 mA: $I \leq 20$ mA at $f \leq 10$ kHz (overflow up to $f_{max} \leq 12$ kHz) $I \leq 100$ mA at $f \leq 100$ Hz
- Active mode uses internal power source: U_{nom} 24 V DC U_o 1.5V @ 10 mA I \leq 20 mA at f \leq 10 kHz (overflow up to f_{max} \leq 12 kHz) I \leq 100 mA at f \leq 100 Hz
- **NAMUR mode** passive to EN 60947-5-6, $f \le 10 \text{ kHz}$, $f_{max} \le 12 \text{ kHz}$
- Scaling Frequency output: in pulses per unit time (e.g. 1000 pulses/s at Q_{100%} Pulse output: in pulses per unit volume (e.g. 100 pulses/m³).
- Pulse width symmetrical, pulse duty factor 1:1, independent of output frequency, automatic, with fixed pulse width, duty factor approx. 1:1 at Q_{100%}, or <u>pulse width von 0.01-2 s</u> adjustable as required for correspondingly low output frequency.
- Forward / reverse flow measurement (F/R mode) is possible, see Fct. C 2.x.06 or 07 Polarity (frequency/pulse output) and Fct. C 2.x.01 Mode (status output).
- Connection diagrams see Sect. 2.7



 Warning!
 All directions, operating data and connection diagrams do not apply to devices used in hazardous areas; in such cases,

 read the special "Ex" operating instructions without fail!

2.5 Status output and limit switches



Depending on the version, the outputs and inputs to be connected passively or actively and/or to NAMUR EN 60947-5-6! The tables in Sect. 2.2 show which I/O version and which inputs and outputs are installed in your signal converter. See also the sticker inside the cover of the terminal compartment. Status output or limit switch can be set under Fct. C 2.1 Hardware.

- All status outputs / limit switches are galvanically separated from all other circuits and from each other.
- Depending on the version, several status outputs / limit switches can be installed in parallel.
- The output stages of the status outputs / limit switches in simple active or passive mode act in the same way as relay contacts and can be connected with any polarities.
- Factory-set data and functions are given in the enclosed report on settings.
- All operating data and functions are adjustable, see Sect. 4.4.

٠	Passive mode	requires external power source:			
		$U_{ext} \le 32V$ DC:	U₀ 1.5V @ 10 mA	$I \le 100 \text{ mA}$	
٠	Active mode	uses the internal power supply:			
		Unom 24 V DC	U₀ 1.5V @ 10 mA:	$I \leq 100 \text{ mA}$	
•	NAMUR mode	passive in conformity with EN 60947-5-6			

• Status output (adjustable to following operating states, see, Fct. C 2.x.01):

- Application error	- output A	Fct. C 2.x.02 appears only
- Uncertain measurement	- output B	when output A - D set under
 Polarity, flow (F/R mode/measurement) 	- output C	Fct. C 2.x.01:
- Overrange, flow	- output D	
- Counter 1 preset value	- off	- sign
- Counter 2 preset value		- overrange
- Empty pipe		- automatic range

• Limit switches (adjustable to following operating states, see Fct. C 2.x.01):

 Flow velocity Volume flow Mass flow 	- Conductivity - Coil temperature
 Setting of limit value and hysteresis Polarity of measured value Time constant 	Fct. C 2.x.02 Fct. C 2.x.03 Fct. C 2.x.04

• Connection diagrams, see Sect. 2.7



 Warning!
 All directions, operating data and connection diagrams do not apply to devices used in hazardous areas; in such cases,

 read the special "Ex" operating instructions without fail!

2.6 Control input

Depending on the version, the outputs and inputs to be connected passively, i actively and/or to NAMUR EN 60947-5-6. The tables in Sect. 2.2 show which I/O version and which inputs and outputs are installed in your signal converter. See also the sticker inside the cover of the terminal compartment. All **control inputs are galvanically separated** from all other circuits and from each other. Depending on the version, two control inputs can be installed in parallel. If two are installed, these have to be set to different functions. In the passive mode, the **control inputs** can be operated with any polarity. Factory-set data and functions are given in the enclosed report on settings. All operating data and functions are adjustable, see Sect. 4.4. Passive mode requires external power source: **U**_{off} 2.5 V DC $U_{ext} \leq 32V DC$: **U**_{on} 19 V DC uses the internal power supply: Active mode Unom 24 V DC Inom 16 mA to EN 60947-5-6 NAMUR mode (Control input active in accordance with NAMUR EN 60947-5-6: open-circuit and short-circuit monitoring to EN 60947-5-6 (NAMUR) can only be done from the infeeding device. Due to the principle involved, only monitoring of control input C_N takes place in the signal converter.) **Status output** (adjustable to following operating states, see Fct. C 2.x.01): - off - zero output + stop Cnt. (not display) - stop all counters - all outputs zero (not display, not counters) - stop counter 1 or 2 - output A, B, C or D zero

- reset all counter 1 or 2
 reset counter 1 or 2
 nold all outputs (not display, not counters)
 hold output A, B, C or D
 hold output A, B, C or D
 range change
- Connection diagrams, see Sect. 2.7

$\mathbf{\Lambda}$	Warning!	All directions, operating data and connection diagrams do not apply to
		devices used in hazardous areas; in such cases, read the special "Ex" operating instructions without fail!

Notes

2.7 Connection diagrams of outputs and inputs

$\mathbf{\Lambda}$	•
Z !N	

• Please note: Depending on the version, connect the outputs and inputs passively, actively and/or to NAMUR EN 60947-5-6.

- The tables in Sect. 2.2 show which I/O version and which outputs and inputs are installed in your signal converter. **Please note the operating data!**
- The following connection diagrams and operating data do not apply to hazardous-duty equipment (EEx); refer to separate operating instructions for such equipment.
- Active mode: The IFC 300 supplies the power for operating (driving) the receiver instruments; note max. operating data.
- **Passive mode:** An external power source (U_{ext}) is required to operate (drive) the receiver instruments.
- All groups are galvanically separated from each other and from all other input and output circuits.
- Terminals that are not used should not have any conductive connection to other electrically conductive parts.
- I_a I_p Current output active or passive
- Pa Pp Pulse / frequency output active or passive
- P_N Pulse / frequency output passive to NAMUR EN 60947-5-6
- $\boldsymbol{S}_{a} \quad \boldsymbol{S}_{b} \quad$ Status output / limit switch active or passive
- S_N Status output / limit switch passive to NAMUR EN 60947-5-6
- C_a C_p Control input active or passive

Milliammeter

· electronic (EC) or

Counter

 C_N Control input active to NAMUR EN 60947-5-6: open-circuit and short-circuit monitoring in accordance with EN 60947-5-6 (NAMUR) can only be done from the infeeding device. Due to the principle involved, only monitoring of control input C_N takes place in the signal converter.

(mA) 000 Σ

____ ¥

Button, N/O contact or similar

electromechanical (EMC)

0 - 20 mA or 4 - 20 mA and others

DC voltage source (U_{ext}) external power supply, any connection polarity


DC voltage source (U_{ext})

Connection polarity as shown in the diagrams



Warning! All directions, operating data and connection diagrams do not apply to devices used in hazardous areas; in such cases, read the special "Ex" operating instructions without fail!


Basic I/O Connection diagrams 1 - 5




Modular I/O and Bus I/O

X marks the terminals A, B, C or D, depending on the version of the IFC 300, see tables in Sect. 2.2.

For electrical connection of the Bus Systems, please consult the separate manuals for i Foundation Fieldbus, PROFIBUS PA oder DP. Current output active I_a (HART[®]) Current output passive I_p (HART[®]) 7 6 IFC 300 IFC 300 $I \le 22 \text{ mA}$ $I \le 22 \text{ mA}$ $\mathbf{R}_{\rm I} < 1 \, \rm k\Omega$ $U_{ext} \leq 32 \text{ V DC}$ х х 'nΑ χ. хmΑ 24 V DC Uext Please note: Only the current output module for terminals C / Ci has HART capability, see Diagrams 16 and 17! Pulse / frequency output active Pa Pulse / frequency output passive Pp 9 8 IFC 300 IFC 300 Uent х х х-000 х-000 Σ Σ 24 V DC f ≤ 10 kHz: I ≤ 20 mA $f \le 10 \text{ kHz}$: $I \le 20 \text{ mA}$ $\mathbf{R} = 1.2 \, \mathrm{k}\Omega \, / \, 0.5 \, \mathrm{W}.$ f ≤ 100 Hz: I ≤ 100 mA $f \le 100 \text{ Hz}$: $I \le 100 \text{ mA}$ only necessary when using electronic totalizer with internal U₀ 1.5 V @ 10 mA U₀ 1.5 V @ 10 mA resistance of **U**nom 24 V DC $U_{ext} \le 32 \text{ V DC}$ $R_i > 5 k\Omega$ 10 Status output / limit switch 11 Status output / limit switch active S_a passive Sp IFC 300 IFC 300 Uext х х хχ. 24 V DC U₀ 1.5 V @ 10 mA U₀ 1.5 V @ 10 mA $I \le 100 \text{ mA}$ $U_{ext} \le 32 \text{ V DC}$ Unom 24 V DC I ≤ 100 mA






HART[®] Circuit diagrams 16 - 17



In the **Basic I/O**, the current output at terminals A+ / A- / A is always HART capable! In the **Modular I/O**, only the current output module for

terminals C / C - is HART-capable!




3 Start-up


- Before connecting to power, please check that the system has been correctly installed in accordance with Sect. 1 and 2.
- The flowmeter, comprising sensor (primary head) and signal converter, is delivered in readyto-operate condition. All operating data have been factory-set according to your order specifications, see supplied report on settings.
- After switching on the power, a self-test is carried out, after which the flowmeter immediately starts flow measurements and the display indicates the current measured values.
- Alternating between the 1st and 2nd measured value window and if provided the list of status messages is carried out by actuating key ↑ or ↓. Possible status messages, their meaning and possible cause are listed in the Status Table in Sect. 4.8.
- The display of the IFC 300 C and IFC 300 F can be turned in steps of 90°. Unscrew the cover of the electronic compartment and remove the two metal clips to the left and right of the display using a screwdriver or similar tool. The display between the metal clips can then be pulled off and re-inserted in the required position. Before pushing the clips together with the display into the electronic compartment, make sure not to kink the display's flat ribbon cable more than absolutely necessary. Replace cover and tighten by hand.

Cover threads to be protected from dirt and well greased at all times; This is particularly important for hazardous-duty (Ex) versions.

4 Operator control of the signal converter

4.1 Display, operating and control elements





- **1** Graphics display, backlit (white)
- 2 1st and 2nd display line to indicate different measured variables, shown here in large format for only one measured variable
- 3 3rd display line, shown here as bar graph
- **4 Optical keys** for operating the signal converter without opening the housing
- 5 Blue bar indicates ...

6

- the tag no. in the measuring mode
- the menu/ function name in the setting mode
- X indicates actuation of a key

indicates IR transmission in operation; the 4 optical keys then have no function

- **7** A signals a status message in the status list
- 8 Socket for connection to the KROHNE GDC bus
- 9 Optical interface for wireless transfer of data (input / output)
- 1 A indicates status messages, if any
- 2 Marker indicates position in the menu/function lists
- **3** Higher-level menu (with No. in Setup Menu only)
- 4 Indicate beginning and end of menu/function lists
- 5 Current menu, open with \rightarrow
- 6 Not indicated in Menu Mode
- 7 Next selectable menu

8 Current menu/function (with No. only in Setup Menu)

- 9 Indicator for factory settings
- **10** Factory setting (for info only, unalterable) of current (sub-) function to be changed
- **11** Current (sub-) function, open with \rightarrow
- 12 Currently set value, unit or function (when selected, shown as white characters on blue background)
- 13 Indicator for allowable range of values
- **14** Allowable range of values, only in case of numerical values or next function

15 Indicator for changing a (sub-) function; allows simple check of changed data when scrolling through the (sub-) function lists.


4.2 Function of keys

Keys	Meas. mode	Menu mode	Function mode	Data mode
*	Alternate between display measured value pages 1 + 2 and status list(s), if provided	Select menu	Select function or (sub) function	Blue cursor • change <u>number</u> • change <u>unit</u> • change <u>property</u> • change <u>decimal point</u>
>	mode to menu mode, press key for 2.5 s,	Entry into selected menu displayed, then 1 st function of menu displayed		For numerical values, move cursor (blue) one place to the right
Ļ		Return to measuring mode, preceded by query whether changed data to be accepted	Press 1 - 3 times, return to menu mode with data acceptance	Return to function or subfunction with acceptance of data
Esc (> ▲)	-	-	Return to menu mode without data acceptance	Return to function or subfunction without data acceptance

Time-out function

- <u>in Operator Control mode</u> After **5 minutes** without key op., return to meas. mode, without acceptance of prev. changed data.
- <u>in Test Menu mode</u> after **60 minutes** without key op., return to meas. mode without acceptance of prev. changed data.
- with GDC IR-Interface mode After the IR-Interface has been activated in Fct. 4.7.06, the interface must be correctly positioned and affixed with the suction cups on the pane of the housing within **60 seconds.**

Mounting: GDC IR - Interface




Optical IR-Interface for PC-supported communication with the signal converter; adapter for the optical interface option: see Sect. 4.4, Fct. 4.7.06.



Please note: The operating point of the 4 optical keys is located directly behind the glass pane. The most reliable way is to actuate the keys perpendicular to the front. Actuation from the side can lead to inadvertent wrong operation.

4.3 Structure of KROHNE program for EMFs



KROHNE

4.4 Table of settable functions

- For your guidance, all menus and functions in the following tables are marked with letters and numbers.
- NOTE! These markings appear in the display only in Setup Menu C.

A Quick Setup - Level

No.	Text displayed	Description and settings	
A 1	Language	Description as for C 4.2.01	
A 2	Measuring point	Description as for C 4.1.01	
A 3	Error reset	Description as for C 4.6.01	
A 4	Unit	Description as for C 4.7	
A 5	Measuring range	Description as for C 2.x.06	Settings act only on the HART [®] capable
A 6	Time constant	Description as for C 2.x.10	current output conn. to Term. A or C (x = terminal for current output:
Α7	Low flow cutoff	Description as for C 2.x.09	2 = Term. A, 4 = Term. C
A 8	Unit for pulse value	Description as for C 2.5.05	Settings act only on the pulse output
A 9	Value per pulse	Description as for C 2.5.06	conn. to Term. D
A 10	GDC IR interface	Description as for C 4.6.06	

B Test - Level

CAUTION! In this mode, outputs indicate the test values, not the measured values. Therefore, if receiver instrumentation connected up, observe plant safety regulations! Switch off alarms, set regulators to manual control, etc.

r		
No.	Text displayed	Description and settings
В 1	Flow velocity	
	Simulation of flow	• Set value confirm with ل and set value Range: -12.00 +12.00 m/s, confirm with ل • No • Yes select and confirm or start test with ل , Value is indicated - Terminate test with ل • Cancel Exit test function with ل
B 2	Volume flow	Same as B1 above but with selected vol. unit, see Fct. C 4.7.01
		In the following descriptions of outputs/inputs, " x " stands for one of the 4 terminals A, B. C or D (Fct. No. B 3 - B 6)
Вх	Current output x	For control of these test functions see B 1 "flow velocity" above, but with
Вх	Frequency output x	appropriate physical unit:: • current output in mA, • frequency output in Hz,
Вх	Pulse output x	 pulse output in pulses/unit. The set value is present at the output Note that max. frequency is 10 Hz (pulses) for electromechanical counters!
Вх	Status output x	Simulation A, B, C or D: • off • cancel • on
Вх	Limit switch x	select and confirm with J
Вх	Control input x	• No • Yes confirm or start simulation with ⊣ , Status is indicated: 0 = off / 1 = on - Terminate test with ⊣
B 7	Operating hours	Indicate the current value, Exit display with ↓
B 8 B 9 B 10 B 11 B 12 B 13	Act. flow speed Act. coil temp. Electron. temp. Act. conductivity * Act. electr. noise * Act. flow profile *	"current measured values" indication (* only visible when Fct. C 1.3.01, C 1.3.13 and C 1.3.10 activated) Terminate indication(s) with 니

C Setup - Level

CAUTION!

When set functions and values are changed, output values and displayed values can change abruptly. Therefore if receiver instrumentation connected up, observe plant safety regulations! Switch off alarms, set regulators to manual control, etc.

No.	Text displayed	Description and settings
C 1	Process input	
C 1.1	Calibration	
C 1.1.01	Zero calibration	 Display of current zero value, continue with →, Query: calibrate zero? <u>Select with ↑ or ↓ :</u> Cancel return with ↓. Automatic continue with ↓, time counts down, measurement of current flow velocity for new zero value. Standard press ↓ to set to factory-set zero value. Manual continue with ↓, display of last set value, use → ↑ ↓ to set new value (range -1 m/s < zero < +1 m/s), (preferably use "Automatic", Before calibration, set "zero" flow in the pipeline!)
C 1.1.02	Size	Select from table: • DN 2.5 - 3000 mm [= 0.1 - 120 inch]
C 1.1.03	GK selection	Select: • GK + GKL • GK • GKL • GKH Set acc. to sensor nameplate.
C 1.1.04	GK	C 1.1.04, 05 or 06 will appear, depend. on selection in Fct. C 1.1.03
C 1.1.05	GKL	<u>Set value:</u> • 0.5 ≤ value ≤ 12 (20)
C 1.1.06	GKH	Set value(s) given on nameplate of connected sensor.
C 1.1.07	Coil resistance Rsp.	• xxx.xx Ohm (setting range 10 ohms < value < 220 ohms at 20°C)
	Calib. coil temp.	Calibration of field coil temperature indicator, Continue with →, "Set coil temp.", select with ↑ or ↓ : • Cancel return with ↓ • Automatic continue with ↓, display of current coil temperature, Set with → ↑ ↓ (range -40.0+200 °C / -40+390 °F). • Standard press ↓ to set to standard value = 20°C Display "Enter resistance", select with ↑ or ↓ : • Cancel return with ↓ • Automatic continue with ↓ measure and set to current coil resistance, continue with ↓ • Standard press ↓ to set to value from Fct. C 1.1.07 (see above)
C 1.1.09	Density	To calculate mass flow at constant density of product • x.xxx kg/l (setting range 0.1 kg/l < value < 5.0 kg/l equivalent to 0.8 lb/gal < value < 4.2 lb/gal)
C 1.1.10	Target conductivity	Set reference value for calibration, range 1.000 9999 µS/cm
C 1.1.11	EF electr. factor	For conductivity indication "calibrate EF?" (values can be changed!) <u>Select:</u> • Cancel • Automatic • Standard • Manual (accept with ↓) • xx.xx mm (setting range 0.10 mm ≤ value ≤ 30.00 mm equivalent to 0.004" ≤ value ≤ 01.20 ")
	Number of electrodes	Select: (see sensor nameplate for details) • 2 electrodes (standard) • (optional) 3 or 4 electrodes
	Field frequency	= line frequency × value (from following list), <u>Select</u> (see sensor nameplate) • $2 \cdot {}^{4}I_{3} \cdot {}^{2}I_{3} \cdot {}^{1}I_{2} \cdot {}^{1}I_{4} \cdot {}^{1}I_{6} \cdot {}^{1}I_{8} \cdot {}^{1}I_{12} \cdot {}^{1}I_{18} \cdot {}^{1}I_{36} \cdot {}^{1}I_{50}$
	Select settling (for special applications)	Select: • Standard (fixed allocation) • Manual (settling time field current) enter time manually
C 1.1.15	Settling time	only when "Manual" selected under C 1.1.14: • xxx.x ms (setting range 1 ms ≤ value ≤ 250 ms)
C 1.1.16	Line frequency	Select: • Automatic • 50 Hz • 60 Hz



CAUTION

When set functions and values are changed, output values and displayed values can change abruptly. Therefore if receiver instrumentation are connected up, observe plant safety regulations. Switch off alarms, set regulators to manual control, etc.

No.	Text displayed	Description and settings
C 1.2	Filter	
C 1.2.01	limitation	All flow values (incl. peaks) limited to set value, before smoothing by time constant • - xxx.x m/s + xxx.x m/s (1st value < 2nd value) Setting range 1st value: - 100.0 m/s ≤ value ≤ - 0.001 m/s 2nd value: + 0.001 m/s ≤ value ≤ + 100.0 m/s equivalent to 1st value: - 328.1 ft/s ≤ value ≤ - 0.001 ft/s 2nd value: + 0.001 ft/s ≤ value ≤ + 328.1 ft/s
C 1.2.02	Flow direction	Define polarity of flow values <u>Select:</u> • normal direction (= direction of arrow on sensor) • opposite direction
C 1.2.03	Time constant	• xxx.x s (setting range 000.0 s < value < 100.0 s) acts on all flow displays and outputs
C 1.2.04	Pulse filter	Select: • off • on (suppresses noise due to solids, air/gas bubbles and sudden changes in pH)
C 1.2.05	Pulse width	Appears only when Fct. C 1.2.04 activated! • xxx.x s (setting range 0.01 s < value < 10 s) length of interference/delays to be suppressed on sudden changes in flow.
C 1.2.06	Pulse limitation	Appears only when Fct. C 1.2.04 activated! • xxx.x m/s (setting range 0.01 s < value < 100 m/s) dynamic limitation from one measured value to the next
C 1.2.07	Noise filter	Select: • off • on (suppresses noise at low conductivity, high solids contents, many air/gas bubbles and chemically inhomogeneous media)
C 1.2.08	Noise level	Appears only when Fct. C 1.2.07 activated! • x.xxx m/s (define noise range: 0.010 m/s < value 10.00 m/s equivalent to 0.032 ft/s < value 32.81 ft/s)
C 1.2.09	Noise suppression	Appears only when Fct. C 1.2.07 activated! • 1 10 set noise suppression factor
C 1.2.10	Low flow cutoff	• x.xxx m/s \pm x.xxx m/s (setting range 0.000 m/s < value < 10.00 m/s) 2 nd value (= hysteresis) $\leq 1^{st}$ value / acts on all outputs



CAUTION

When set functions and values are changed, output values and displayed values can change abruptly. Therefore, if receiver instrumentation is connected up, observe plant safety regulations. Switch off alarms, set regulators to manual control, etc.

No.	Text displayed	Description and settings
C 1.3	Self test	
C 1.3.01	Empty pipe	 OFF Conductivity (conductivity measurement ON) Cond.+empty pipe [A] (cond.meas. and empty pipe indication) Error category "Application": Flow indication "zero" when pipe empty Cond.+empty pipe [U] (cond.meas. and empty pipe indication) Error category "uncertain measurement": Flow indication "not zero" when pipe empty
C 1.3.02	Limit empty pipe	Appears only when "Cond. + empty pipe []" activated in Fct. C 1.3.01 • xxx.x μS/cm (setting range 0.0 μS/cm < value < 9999 μS/cm) Here, set max. 50% of the lowest conductivity occurring in operation, "Empty pipe" is indicated when conductivity drops below set value in the measuring mode
C 1.3.03	Act. conductivity	Display of current conductivity (only when Fct. C 1.3.01 is activated)
C 1.3.04	Full pipe	off • on by way of electrode impedance measurement (see Fct. C 1.1.08) Note: Fct.C1.3.03+04 only with special sensor version - 4 electrodes!
C 1.3.05	Limit full pipe	Appears only when "full pipe" activated in Fct. C 1.3.04 • xxx.x μS/cm (setting range 0.000 μS/cm ≤ value ≤ 9999 μS/cm)
C 1.3.06	Linearity	• off • on Linearity test with 2 field currents, (appears only when GK and / or GKL set, see Fct. C 1.1.03)
C 1.3.07	Act. linearity	Display of current linearity (only when Fct. C 1.3.06 activated)
C 1.3.08	Gain	• off • on (cyclic test incl. analog preamplifier)
C 1.3.09	Coil current	• off • on (cyclic test of field current)
C 1.3.10	Flow profile	• off • on (test of flow profile via inhomogeneous magnetic field)
C 1.3.11	Limit flow profile	Appears only when "flow profile" activated in Fct. C 1.3.10• $xx.xxx$ (setting range: $0.000 \le value \le 10.000$)This value determines the degree of distortion for an error message
C 1.3.12	Act. flow profile	Display of the current value (only when Fct. C 1.3.10 activated)
C 1.3.13	Electrode noise	on (test of electrode voltage noise)
C 1.3.14	Limit noise	• xxx.x m/s (setting range: 0.000 m/s ≤ value ≤ 12.000 m/s equivalent to 0.000 ft/s ≤ value ≤ 39.370 ft/s)
C 1.3.15	Act. electr. noise	Display of the current noise reading (only when Fct. C 1.3.13 activated)
C 1.3.16	Settling of field	• off • on
C 1.4	Information	
C 1.4.01	Liner	Select from list, set according to details on sensor nameplate
C 1.4.02	Electr. material	Select from list, set according to details on sensor nameplate
C 1.4.04	Serial no. sensor	Setting as indicated on sensor nameplate
C 1.4.05	V No. sensor	Setting as indicated on sensor nameplate
C 1.5	Simulation	
C 1.5.01	Flow speed	Sequence, see Test Level Menu, Fct. B 1 above
C 1.5.02	Volume flow	Sequence, see Test Level Menu, Fct. B 2 above

No.	Text displayed	Description and settings	
C 2	1/0		
C 2.1	Hardware		
C 2.1.01	Terminals A	Assignment of terminals A - D dependent on IFC 300 version:	
C 2.1.02	Terminals B	Outputs: • current • frequency • pulse • status • limit value	
C 2.1.03	Terminals C	Input: • control	
C 2.1.04	Terminals D	• off (input and/or output switched off)	
		In the following descriptions of the current output, " x " denotes the <u>terminals</u> : C 2. 2 = <u>A</u> C 2. 3 = <u>B</u> C 2. 4 = <u>C</u>	
C 2.x	Current output X		
C 2.x.01	Range 0% 100%	• xx.x xx.x mA (setting range 0.00 mA \leq value \leq 20.0 mA) 0 mA \leq 1 st value \leq 2 nd value \leq 20 mA	
C 2.x.02	Extended range	• xx.x xx.x mA (setting range 3.5 mA \leq value \leq 21.5 mA) 0 mA \leq 1 st value \leq 2 nd value \leq 21.5 mA	
C 2.x.03	Error current	• xx.x mA (setting range 0.00 mA ≤ value ≤ 22.0 mA) 0 mA ≤ value ≤ 25 mA (outside the overrange)	
C 2.x.04	Error condition	Application fault • fault in device • uncertain measurement condition for fault current: fault in the selected and in higher fault categories, see Sect. 4.10	
C 2.x.05	Measurement	Volume flow rate • mass flow rate • coil temperature • flow velocity • conductivity • off	
C 2.x.06	Range	0 xx.xx (format and unit dependent on measured variable, see C 2.x.05)	
C 2.x.07	Polarity	both polarities • positive polarity • negative polarity • absolute choice of meas. value polarity, note flow direction, see C 1.2.02	
C 2.x.08	Limitation	± xxx ± xxx % (setting range -150 % ≤ value ≤ +150 %)	
C 2.x.09	Low flow cutoff	xx.x ± xx.x % (setting range: 0.0 % 20 %) 1st value = operating point 2nd value = hysteresis (condition: 2nd value ≤ 1st value)	
C 2.x.10	Time constant	xxx.x s (setting range 000.1 s 100.0 s)	
C 2.x.11	Special function	OFF (= switched off) Automatic range (= switched on) for indication Activate status output accordingly External range (= switched on) for external range change Activate control input accordingly	
C 2.x.12	Range setting	Appears only when Fct. C 2.x.11 activated, see above. Set switching point for automatic range or external range; defines the rangeability xx.x ± xx.x % (setting range: 5.0 % 80 %) 1st value = operating point 2nd value = hysteresis (condition: 2nd value ≤ 1st value)	
C 2.x.14	Simulation	Sequence, see Test Level Menu, Fct. B 1 above	

No.	Text displayed	Description and settings		
		In the following descriptions for the frequency output, " x " denotes the <u>terminals</u> : C 2.2 = \underline{A} C 2.3 = \underline{B} C 2.5 = \underline{D}		
C 2.x	Frequency output X			
C 2.x.01	Pulse shape	• automatic approx. pulse width in [ms] = visual base of the symmetrical pulse duty factor 500 / (max. pulse rate in [1/s]) approx. 1:1 2.x.02		
C 2.x.02	Pulse width	Appears only when "fixed" activated in Fct. C 2.x.01 Pulse Shape, see above xxx.xx ms (setting range: 0.05 2000 ms) (Note: max. setting value T_0 [ms] \leq 500.00 / (max. pulse rate [1/s])		
C 2.x.03	100 % Pulsrate	xxxxx.x 1/s (setting range 00000.00 10000.0 1/s) limitation at 100% pulse rate ≤ 100 / s: $I_{max} \leq 100$ mA limitation ati 100% pulse rate > 100 / s: $I_{max} \leq 20$ mA		
C 2.x.04	Measurement	volume flow volume fl		
C 2.x.05	Range	0 100% (= unit dependent on measured variable selected)		
C 2.x.06	Polarity	both polarities • positive polarity • negative polarity • absolute choice of meas. val. polarity, note flow direction, see C 1.2.02		
C 2.x.07	Limitation	-xxx +xxx % (setting range -150% +150%)		
C 2.x.08	Low flow cutoff	xxxx.x \pm xxxx.x unit dependent on measured variable selected 1st value \geq 2nd value (hysteresis), values around "0" are set to "0"		
C 2.x.09	Time constant	xxx.x s (setting range 000.0 100.0 s)		
C 2.x.10	Invert signal	Select:• off(= switch closes on every pulse, normally open)• on(= switch opens on every pulse, normally closed)		
C 2.3.11	Special function	This function is only available in devices with 2 frequency outputs connected to terminals "B" and "D", see Fct. 2.5.11 below! <u>select:</u> • off (= no special function) • Phase shift to D (= setting of all functions for output B via output D)		
	Phase shift	This function is only available in devices with 2 frequency outputs connected to terminals B and D, see Fct. 2.3.11 above! <u>Select:</u> • off (= no phase shift between output B + D) • 0° shift (signal inversion possible) • 90° shift (signal inversion possible) • 180° shift (signal inversion possible) When Fct. C 2.5.06 Polarity is set to "both polarities", the flow direction is indicated (e.g. +90° or -90°).		
C 2.x.13	Simulation	For sequence, see Test Level Menu, Fct. B 1 above		

No.	Text displayed	Description and settings		
		In the following descriptions for the pulse output, " \mathbf{x} " denots the <u>terminals</u> : C 2.2 = A C 2.3 = B C 2.5 = D		
C 2.x	Pulse output X			
C 2.x.01	Pulse shape	• automatic approx. pulse width in [ms] = 500 / (max. pulse rate in [1/s]) • fixed duty factor 1:1 • fixed set Fct. C 2.x.02		
C 2.x.02	Pulse width	Appears only when "fixed" activated in Fct. C 2.x.01 Pulse Shape, see above xxx.xx ms (setting range: 0.05 2000 ms) (Note: max. setting value T_p [ms] \leq 500.00 / (max. pulse rate [1/s])		
C 2.x.03	100% pulse rate	$\begin{array}{llllllllllllllllllllllllllllllllllll$		
C 2.x.04	Measurement	volume flow • mass flow		
C 2.x.05	Pulse value unit	Selection of unit from one of the lists, dependent on measured variable		
C 2.x.06	Pulse p.value	xxx.xxx set for volume or mass per pulse lowest settable pulse value meas.range [in I/s or kg/s] 100% pulse rate [in 1/s] (see Fct. C 2.x.03 for pulse output)		
C 2.x.07	Polarity	• both polarities • positive polarity • negative polarity • absolute choice of meas.value polarity, note directionn of flow, see C 1.2.02		
C 2.x.08	Low flow cutoff	xxxx.x ±xxxx.x unit dependent on meas. variable selected 1st value $\ge 2^{nd}$ value (hysteresis), values around "0" are set to "0"		
C 2.x.09	Time constant	xxx.x s (setting range 000.0 100.0 s)		
C 2.x.10	Invert signal	Select: • off (= switch closes on every pulse, normally open) • on (= switch opens on every pulse, normally closed)		
C 2.3.11	Special function	This function is only available when devices have 2 frequency outputs connected to terminals "B" and "D", see Fct. 2.5.11 below! <u>Select:</u> • off (= no special function) • Phase shift to D (= all functions set for output B via output D)		
C 2.5.11	Phase shift	This function is only available when devices have 2 frequency outputs connected to terminals B and D, see Fct. 2.3.11 above! Select: • off (= no phase shift between outputs B+D) • 0° shift (signal inversion possible) • 180° shift (signal inversion		
C 2.x.13	Simulation	Procedure, see Test Level Menu, Fct. B 1 above		

No.	Text displayed	Description and settings		
		In the following descriptions of the outputs/inputs, " x " denotes the <u>terminals</u> : $C 2.2 = A / C 2.3 = B / C 2.4 = C / C 2.5 = D$ (control input connected only to terminals A and B)		
C 2.x	Status output X			
C 2.x.01	Mode	 application error uncertain measurem. polarity, flow overrange, flow output D empty pipe counter 1 preset counter 2 preset output D output D 		
C 2.x.02	"Output or input"	Appears only when "output A, B, C or D" activated in Fct. C 2.x.01 Mode, see above.		
	Dependent on selection under Fct. 2.x.01, see	• same signal (only when there are 2 status outputs)		
	above	• sign	Selection	
		• over range	dependent on	
		• automatic range (appears only if set to current output X in Fct. C 2.x.01, see status output above)	input or output combination	
		• off		
C 2.x.03	Invert signal	Select: • off (= switch closes on every pulse, normally open) • on (= switch opens on every pulse, normally closed)		
C 2.x.05	Simulation	Sequence, see Test Level Menu, "B x" above (X depends on terminal)		
C 2.x	Limit switch X			
C 2.x.01	Measurement	volume flow • mass flow • coil temperature flow speed • conductivity		
C 2.x.02	Limit	xxx.x \pm x.xxx (set limit value, hysteresis) format, unit acc. to meas. range selected and its upper range value. 2 nd value (= hysteresis) < 1 st value		
C 2.x.03	Polarity	both polarities • positive polarity • negative polarity • absolute choice of meas.value polarity, note direction of flow, see C 1.2.02		
C 2.x.04	Time constant	xx.x s (setting range 000.0 100.0 s)	xx.x s (setting range 000.0 100.0 s)	
0 0 - 0 -		Select: • off (= switch closes on every pulse, normally open) • on (= switch opens on every pulse, normally closed)		
C 2.X.05	Invert signal	• on (= switch opens on every pulse, normal	ly closed)	
C 2.x.05 C 2.x.07	Invert signal Simulation		ly closed)	
	-	• on (= switch opens on every pulse, normal	ly closed)	
C 2.x.07	Simulation	• on (= switch opens on every pulse, normal Sequence, see Test Level Menu, "B x" above (X depends of Connected to terminals A and/or B only • off • hold all outputs • stop zero output + cnt. (not display, not co (not display) • hold output A, B, • stop all counters • all outputs zero • stop counter 1 or 2 (not display, not co • reset all counters • output A, B, C or • reset counter 1 or 2 • range change • error reset Note! If two control inputs are provided, they should not b	y closed) in terminal) ounters) C or D ounters) D zero e set to the same	
C 2.x.07 C 2.x C 2.x.01	Simulation Control input X Mode	 on (= switch opens on every pulse, normal Sequence, see Test Level Menu, "B x" above (X depends of Connected to terminals A and/or B only off hold all outputs hold all outputs (not display) 	y closed) in terminal) ounters) C or D ounters) D zero e set to the same	
C 2.x.07 C 2.x C 2.x.01	Simulation Control input X	 on (= switch opens on every pulse, normal Sequence, see Test Level Menu, "B x" above (X depends of Connected to terminals A and/or B only off • hold all outputs off • hold all outputs (not display) • hold output 4, B, stop all counters • stop counter 1 or 2 (not display, not cordisplay, not cordis	lý closed) on terminal) ounters) C or D ounters) D zero be set to the same ed to Term. A is in	

No.	Text displayed	Description and settings		
C 2.6 C 2.7	Counter 1 and / or Counter 2	All functions and settings for both counters are the same! In the following descriptions the "y" indicates the counter: • Counter 1 = C 2.6 • Counter 2 = C 2.7		
C 2.y.01	Function of counter	• + counter • - counter • sum counter • off		
C 2.y.02	Measurement	Select: • volume flow • mass flow		
C 2.y.03	Low flow cutoff	xxxx.x \pm xxxx.x unit dependent on measured variable selected 1st value \geq 2nd value (hysteresis), values around "0" are set to "0"		
C 2.y.04	Time constant	xx.x s (setting range 000.0 100.0 s)		
C 2.y.05	Preset value	x.xxxx in the unit selected , max. 8 places (see Fct. C 4.7.10 or 13), set the status output (see Fct. C 2.x.01) for signalling to counter 1 / 2 preset value		
C 2.y.06	Reset counter	Select: • yes • no		
C 2.y.07	Set counter	Set initial counter value (overwrites current reading) <u>Select:</u> • cancel ب / return without simulation • set value ب / set value / ب / then query "set counter?" No - Yes / select, execute with با		
C 2.y.08	Stop counter	Select: • yes • no		
C 2.y.09	Start counter	Select: • yes • no		

C 3	Communication		
C 3.1	HART		
C 3.1.01	Address	Address range 0-15, Address 0: current output with Addresses 1-15: multidrop. Current output fixed at	
C 3.1.02	4 mA trimming	Set 4 mA value (setting range 3.6 5.5 mA)	4 / 20 mA: reset to
C 3.1.03	20 mA trimming	Set 20 mA value (setting range 18.5 21.5 mA)	factory calibration
C 3.1.04	Message	Texts of choice can be set (up to 32 places)	
C 3.1.05	Description	Texts of choice can be set (up to 16 places)	

C 4	Device		
C 4.1	Device info		
C 4.1.01	Тад	Measuring point identifier (Tag No.) , also applies to HART [®] address (see C .3.1.1) also appears in the display header (up to 8 places)	
C 4.1.02	C number	Electronic unit-No. (see signal converter nameplate) / unalterable	
C 4.1.03	Device serial no.	Serial No. of the system / unalterable	
C 4.1.04	Electronic serial no.	Serial No. of the complete electronic unit	
C 4.2	Display		
C 4.2.01	Language	Select: • English • Deutsch • Français • others in preparation	
C 4.2.02	Contrast	Setting range: -9 0 +9	
C 4.2.03	Default meas. page	Select: • 1st meas. page • 2nd meas. page • none • status page	

No.	Text displayed	Description and settings		
	1 st meas. page 1			
C 4.3	and / or	All functions and settings for the two pages are identical! In the following descriptions "z" characterizes		
C 4.4	2 nd meas. page 2	the m.v. page: \cdot page 1 = C 4.3 \cdot page 2 = C 4.4		
C 4.z.01	Function	• one line • two lines • three lines		
C 4.z.02	Measurement 1 st line	 flow speed 	• coi	il temperature
		volume flow • conductivity		
		• mass flow		
C 4.z.03	Range	Unit and format depend	on measured qua	ntity selected under C 4.z.02
C 4.z.04	Limitation	xxx % (100 % ≤ va	lue ≤ 999 %)	
C 4.z.05	Low flow cutoff	xxxx.x \pm xxxx.x un 1st value \geq 2nd value (hy		easured variable selected ound "0" are set to "0"
C 4.z.06	Time constant	xxx.x s (setting rang	ge 000.0 100.0 s	5)
C 4.z.07	Format 1 st line	Setting of dec. places a	cc. to list: • X (none	e) X.XXXXXXXX (8 places)
C 4.z.08	Measurement 2 nd line		oil temperature ounter 1	Operating hours
			ounter 2 ar graph	Selection dependent on Function C 4.z.01
C 4.z.09	Format 2 nd line	Setting of dec. places a	cc. to list: • X (none	e) X.XXXXXXXX (8 places)
C 4.z.10	Measurement 3 rd line	flow speed • conductivity • counter 1 • volume flow • coil temperature • counter 2 • mass flow • Operating hours		
C 4.z.11	Format 3 rd line	Setting of dec. places a	cc. to list: • X (none	e) X.XXXXXXXX (8 places)
C 4.6	Special functions		·	
C 4.6.01	Error reset	Select: • No • Yes (reset errors that are not automatically deleted, such as "line failure", "counter overflow", etc.)		
C 4.6.02	Save settings	• Backup 1 • Backup 2 select, then press ↓ • No • Yes confirm with ↓ or start Backup • Cancel exit Backup function with ↓ With this function, complete device data records can be written into the Backup 1, 2 memories and from there be reloaded (see below)		
C 4.6.03	Load settings	• Factory settings • Backup 1 • No	load settings	• Factory settings • Backup 1 • No
C 4.6.04	Password Quick Set	Activates 4-character p 0000 deactivates the pa		ges in the Quick Setup Menu.
C 4.6.05	Password Setup	Activates 4-character password for changes in the Setup Menu and in the Test Menu. 0000 deactivates the password.		
C 4.6.06	GDC IR interface	Select: • cancel	Press 🗸 key, IR-In	terface not activated, and
			exit this function	
			key, IR-S اله key, IR-S accept all changes	ensor is activated, and made up to now
		Within the next 60 sec. position the IR-Interface with the suction cups on the pane of the housing. The correct position is indicated by the steady bright red LED of the interface, as soon as the red LED and the IR-Sensor (below the keys on the display) are roughly one above the other, see Fig. in Sect. 4.2.		ps on the pane of the housing. n is indicated by the steady he interface, LED and the IR-Sensor (below splay) are roughly one above the

No.	Text displayed	Description and settings		
C 4.7	Units	(units applicable to display and all settings, except for pulse output)		
C 4.7.01	Volume flow	I/s • m³/s I/min • m³/min I/h • m³/h user-defined unit (free unit)	• ft³/s • gal/s • IG/s • ft³/min • gal/min • IG/min • ft³/h • gal/h • IG/h	
	Text free unit	 appear only when "fr 	ee unit" selected in Fct. C 4.7.01	
C 4.7.03	[m ³ / s] * Factor	to set these two function	ns, see "free unit " below	
C 4.7.04	Mass flow	• g/s • kg/s • g/min • kg/min • t/min • g/h • kg/h • t/h • user-defined unit (free unit)	 Ib/s ST/min (= Short Ton) Ib/min ST/h Ib/h LT/h (= Long Ton) 	
C 4.7.05	Text free unit	appear only when "free unit" selected in Fct. C 4.7.04		
C 4.7.06	[kg / s] * Factor	 to set these two function 	ns, see "free unit " below	
C 4.7.07	Flow speed	• m/s	• ft/s	
C 4.7.08	Conductivity	• µS/cm • S/m		
C 4.7.09	Temperature	•K •°C	• °F	
C 4.7.10	Volume	• ml • l • hl • m ³ • user-defined unit (free unit)	• in³ • ft³ •yd³ • gal • IG	
C 4.7.11	Text free unit	appear only when "free unit" selected in Fct. C 4.7.10		
C 4.7.12	[m ³] * Faktor	 to set these two function 	ns, see "free unit " below	
C 4.7.13	Mass	• mg • g • kg • t • user-defined unit (free unit)	•oz •lb •ST (Short Ton) •LT (Long Ton)	
C 4.7.14	Text free unit	 appear only when "fr 	ree unit" selected in Fct. C 4.7.13	
C 4.7.15	[kg] * Factor	• to set these two functions, see "free unit" below		
C 4.7.16	Density	• kg/m³ • kg/l	• lb/ft³ • lb/gal	
		 user-defined unit (free unit) 		
C 4.7.17	Text free unit	• appear only when "fr	ee unit" selected in Fct. C 4.7.16	
C 4.7.18	[kg / m³] * Factor	 To set these two functions, see "free unit" below 		

Free (user-defined) unit

Set required texts:	 for volume rate of flow, mass rate of flow and density: max. 3 characters before and max. 3 characters after the slash
	 for volume and mass: max.3 characters
	- characters useable: az / AZ / 09 / . , " + - * / # @ \$ % ~ () []
Set conversion factor:	 wanted unit = [unit, see above] × conversion factor conversion factor: max. 9 digits shift decimal point with ↑ (to left) and with ↓ (to right)

4.5 To reset counters

Key	Text displa	yed	Description and settings
\rightarrow	A	Quick Setup	Countdown from 2.5 s to 0.0 s, then release key
$\uparrow \rightarrow \downarrow$	C 2	1/0	
\rightarrow	C 2.1	Hardware	
→ <u>1× ↑ or</u> 2× ↑	2.7	Counter 2	Select counter that is to be reset
2× ↑	2.6	Counter 1	
\rightarrow	C 2.6.01	Counter function	
4× ↑	C 2.6.06	Reset counter?	
\rightarrow	C 2.6.06	Reset counter	<u>Select with ↑ or ↓:</u> • No
4	C 2.6.06	Reset counter	Counter has been reset
4× ₊		Measuring mode	

4.6 To delete error messages (for list of possible error messages, see Sect. 4.10)

1st Possibility in the "Quick Setup" menu"


Key	Text displayed	Description and settings
\rightarrow	Quick Setup	Countdown from 2.5 s to 0.0 s,
_		then release key
\rightarrow	Language	
2× ↑	Reset error	
\rightarrow	Reset? No	
1	Reset? Yes	
4	Reset error(s)	Errors have been reset
2×	Measuring mode	

2nd Possibility in the "Setup" menu

Key	Text displa	iyed	Description and settings
\rightarrow	А	Quick Setup	Countdown from 2.5 s to 0.0 s,
			then release key
$\uparrow \rightarrow \uparrow \rightarrow$	C 4	Device	
→	C 4.1	Device info	
↑ (or 6× ↓)	C 4.6	Special functions	
\rightarrow	C 4.6.01	Reset error(s)?	
→	C 4.6.01	Reset error(s)?	Select with \uparrow or \downarrow : • No • Yes
Ļ	C 4.6.01	Reset error(s)	Errors have been reset
4× ₊		Measuring mode	

4.7 General directions for special measurements, tasks and diagnostics


4.7.1 Empty measuring tube and electrical conductivity measurement



σ R₌ K EF	electrical conductivity electrode resistance a constant (d) electrode factor, see Fct. C 1.1.11	$R_{E} = \frac{K}{\sigma \times EF}$ $\sigma = \frac{K}{R_{E} \times EF}$
Empty pipe (filling below level of electrodes)		pipe flowing full
• <u>in t</u>	theory_	R _E = ca.1 kΩ 10 MΩ
$\mathbf{R}_{E} \rightarrow \infty \Omega \mid \boldsymbol{\sigma} \rightarrow 0 \ \mu S/cm$		σ = Ca. σ operation
• <u>in practice</u> (wetted tube wall) R _E = approx. 3× Roperation		


 σ = approx. ¹/₃ σ _{operation}

4.7.2 Measurement of coil temperature by way of the resistance of the field coils (dependent on ambient and product temperatures)



4.7.3 To measure and identify the flow profile

(empty meas. tube / deposits / defective liner / improper installation / etc.)



- I₁ field current, upper coil
- U₁ electrode voltage resulting from I₁
- I₂ field current, lower coil
- U_2 electrode voltage resulting from I_2

 I_1 and I_2 generate opposing magnetic fields in the upper and lower half of the tube. The resultant voltages U_1 and U_2 can be picked off at the electrodes.

 $U_1 - U_2 = 0$ symmetrical, undisturbed flow profile

$U_1 \neq U_2$

unsymmetrical or disturbed flow profile

Possible causes:

- Meas. tube not completely filled
- Deposits on bottom of measuring tube
- Liner of sensor defective
- Improperly installed, gaskets project e.g. into measuring tube

4.8 Special measurements

The following Table shows functions and parameters that need to be set in order to obtain special measured values and indications.

Special measurements	Set the functions Number, unit or property		Effect on Measurement	Status messages
• Conductivity Measurement and indication	<u>C 1.3.01 Empty Pipe</u> Activate with one of the 3 functions for Measurement	 Conductivity Cond.+ empty pipe [A] Cond.+ empty pipe [U] 	Indication of measured values possible via display or outputs	-
• Coil temperature above the allowable limit value	No special settings needed, coil temperature is always measured		Indication of measured values possible via display or outputs	[U] coil temperature
Change of product e.g. stop external counting via pulse output of Medium A = product, Medium B not measured	<u>C 1.3.01 Empty Pipe</u> • Conductivity • Cond.+empty pipe [A] • Cond.+ empty pipe [U] (Activate cond. meas. with one of the 3 functions above)	2.x.01limit switch • set to conductivity 2.x.02 limit value: Set for Medium A: • Cond. Medium A > B Approx. lowest conductivity of A • Cond. Medium A < B approx. highest conductivity of A	Counting stopped; change from Medium A to Medium B signalled via the limit switches	no message

4.9 Special measurement tasks and diagnostics

The following Table shows functions and parameters to be set in order to perform special tasks, diagnostics, and obtain reactions, information, etc. during measurement.

Meas. / task / info / reaction	Set the functions number, unit or property	Effect on measurement	Status messages
• Empty pipe (1) Stop flow indication, flow outputs and flow counting	<u>C 1.3.01Empty Pipe</u> • Cond.+ empty pipe [A] <u>2.x.01limit switch</u> • set to Empty Pipe <u>2.x.02.limit val.</u> • set to approx. ¹ / ₃ of lowest occurring conductivity	Flow indic. = zero , flow outputs = zero , flow counting stopped , cond. indic. = approx. zero	[A] applica- tion error [A] empty pipe
• Empty pipe (2) Flow indication, flow outputs and flow counting remain active	<u>C 1.3.01 Empty Pipe</u> • Cond.+ empty pipe [U] <u>2.x.01 limit switch</u> • set to Empty Pipe <u>2.x.02 limit val.</u> • set to approx. ¹ / ₃ of lowest occurring conductivity	undefined flow indic., flow outputs and flow counting cond. indic. = approx. zero	[U] uncertain meas. [U] empty pipe
• Full pipe (1) Filling level below crown of pipe	<u>C 1.3.10 Flow profile</u> • ON	flow meas. and flow counting continue, accuracy dependent on filling level	[U] uncertain meas. [U] flow profile
• Full pipe (2) Filling level just below crown of pipe (only with 4 electrodes, special sensor version)	<u>C 1.3.04 Full Pipe</u> • ON <u>C 1.3.05 Limit Full Pipe</u> • Set to approx. ¹ / ₃ d of lowest occurring conductivity	counting continue,	[U] uncertain meas. [U] pipe not full
Flow profile ok? Installation inlet/outlet run	<u>C 1.3.10 Flow profile</u> • ON	flow meas. and counting, accuracy dependent on filling level	[U] flow profile
• Liner ok? Shows severe bulging, erosion by abrasive media	<u>C 1.3.10 Flow profile</u> • ON	flow meas. and counting, accuracy dependent on the geometry of the defect	[U] flow profile

Meas. / task	Set the functions		Effect on	Status
info / reaction • Deposits (1) Insulating, on the electrodes	number, u <u>C 1.3.01 Empty Pipe</u> • Cond.+ empty pipe [A] • Cond.+ empty pipe [U]	Init or property 2.x.01 limit switch • set to conductivity 2.x.02 limit val. • set to approx. ¹ / ₃ of lowest occurring conductivity	measurement same as ab empty pipe 1	
Deposits (2) of different thickness, on the electrodes	<u>C 1.3.01 Empty Pipe</u> • Cond.+ empty pipe	U]	undefined flow indication, flow outputs, flow counting and conductivity indication	[U] uncertain meas. [U] electrode symmetry
Deposits (3) on bottom of tube	C 1.3.10 Flow Profile • ON		flow indication and flow counting, accuracy dependent on thickness of deposits and on conductivity	[U] uncertain meas. [U] flow profile
Deposits (4) conductive, on tube inner wall, causing electrode short-circuit		2.x.01 limit switch • set to conductivity 2.x.02 limit val. • set to approx. twice the value of process conductivity	flow indication and flow counting, accuracy dependent on thickness of deposits and on conductivity	-
Electrode coating (1) insulating, stop flow indic., flow outputs and flow counting	<u>C 1.3.01 Empty Pipe</u> • Cond.+ empty pipe [A]	2.x.01 limit switch • set to conductivity 2.x.02 Glimit value • set to approx. ¹ / ₃ of lowest occurring conductivity	flow indication, flow outputs, flow counting stopped , Accuracy of conductivity indication dependent on resistance of coating	tion error
Electrode coating (2) Flow indic., flow outputs and flow counting remain active	<u>C 1.3.01 Empty Pipe</u> • Cond.+ empty pipe [U]	2.x.01limit switch • set to conductivity 2.x.02 limit value • set to approx. ¹ / ₃ of the lowest occurring conductivity	Flow indication, flow outputs, flow counting and cond. indication continue to be active , accuracy dependent on resistance of coating	[U] uncertain meas. [U] pipe empty
Solids in medium Noisy flow indication and flow outputs	C 1.3.13 Electrode noise • ON		If flow indications, flow outputs and counts very noisy, perhaps additionally activate pulse or noise filters, see Fct. C1.2.04 and 07, resp.	[U] electrode noise
Gas bubbles in medium Noisy flow indication and flow outputs	C 1.3.13 Electrode noise • ON C 1.3.14 Limit Electr. Noise • Set e.g. to approx. 0.1× the current flow velocity		If flow indications, flow outputs and counts very noisy, perhaps additionally activate pulse or noise filters, see Fct. C1.2.04 and 07, resp.	[U] electrode noise
Electrode corrosion Noisy flow indic and flow outputs, sensor failure	C 1.3.13 Electrode noise • ON C 1.3.14 Limit Electr. Noise • Set e.g. to approx. 0.01 m/s		If flow = zero and pipeline is flowing full, noise might be an indication of electrode corrosion	[U] electrode noise

4.10 Status messages and diagnostics information

- These messages are shown on page 3 of the display. mA- and status outputs can be set so that error messages are signalled, see Sect. 4.4, Fct. C 2.x.04 (current) and Fct. C 2.x.01 (status).
- Please note: for settings with mA and/or status outputs:

- uncertain measurement
- application error (A)
- fault in device (F)

ent (U) = all errors of Categories U, A and F

= all errors of Categories A and F

= all errors of Category F

Display messages	Description	Possible causes, remedial action Repair necessary !	
status: F (see texts below)	 operational fault in device, mA output ≥ 3.5 mA, Status outputs open, pulse / frequency output: no pulses 		
fault in device	Operational fault in device. Group message, who No measurement possible following or some oth error occurs		
IO 1	Error, operational fault in IO 1. No measurement possible	Try the following: Load settings (Fct. C 4.6.3) (Backup 1 or Backup 2 or factory	
IO 2	Error, operational fault in IO 2, No measurement possible	settings).	
parameter	Error, operational fault in device, Parameters no longer useable No measurement possible	If status message still does not disappear, replace electronic unit.	
Configuration (also when module changed)	Identified configuration differs from the one stored. No measurement possible	After change of module, confirm query for changed configuration. If device configuration unchanged: defective, replace electronic unit.	
display (no longer available)	Error, operational fault in display	Defective, replace electronic unit	
sensor electronics	Error, operational fault in sensor electronics, No measurement possible	Defective, replace electronic unit	
sensor global	Data error in the global data of the sensor electronic equipment No measurement possible	Load settings (Fct. C 4.6.3) (Backup 1 or 2 or factory settings). If status message still does not disappear, replace electronic unit.	
sensor local	Data error in the local data of the sensor electronics. No measurement possible	Defective, replace electronic unit	
field current local	Data error in the local data of the field current supply. No measurement possible	Defective, replace electronic unit	
current output A	Operational fault in current output at the pair of	Defective, replace electronic unit	
current output B	terminals indicated. Measured value at this pair of terminals no longer available	or I/O module.	
current output C			
Operator software	Fault revealed by CRC check of operator software, device not operable.	Replace electronic unit	
Hardware settings	The set hardware parameters do not match the identified hardware. A dialogue appears in the display.	Answer queries in dialogue mode, follow directions.	
Hardware identification	Existing hardware cannot be identified. There are either defects or unknown modules.	Replace electronic unit	
RAM/ROM error IO1	A RAM or ROM error is detected during the CRC		
RAM/ROM error IO2	check.	or I/O module	

Display messages	Description	Possible causes, remedial action	
Status: A (= see texts below	 application-sensitive fault, device OK, measured values affected 	Application test or operator action necessary !	
Application error	Application fault, device OK. Use measured values with caution	Group message, when errors as below or other application errors occur.	
Empty pipe	1 or 2 measuring electrodes are not in contact with the medium: flow indication = 0. Pipe not filled, function dependent on Fct. C 1.3. Monitoring / message only if "cond.+empty pipe [A]" Or electrodes completely by e.g. oil film. Clean!		
Flow rate too high (not when pipe empty)	Overrange, Filter setting limits the measured values	Limitation Fct. C 1.2.01: Increase values	
Field frequency too high (not when coil has open circuit)	Field current has not settled, measured flow value inaccurate	IF Fct. C 1.1.14 Settling Time is set to "Manual", increase value in Fct. C 1.1.15. If "Standard" is set, set field frequency in Fct. C 1.1.13 acc. to sensor nameplate.	
DC Offset (not when pipe empty)	ADC overdriven by DC input level, flow measured value = 0	For IFC 300 F and W: check connection of signal cable	
Open circuit A	Load of current output A too high	Current not correct, mA output cable has open circuit	
Open circuit B	Load of current output B too high	or load too high.	
Open circuit C	Load of current output C too high	Check cable, reduce load (should be < 1000 Ohm)!	
Over range A	Measured value at terminals A limited by filter setting	Check with Fct. C 2.1 Hardware or sticker in terminal compartment,	
Over range B	Measured value at terminals B limited by filter setting	which output is connected to the terminal. If current output:	
Over range C	Measured value at terminals C limited by filter setting	Extend Fct. C 2.x.06 Measuring Range and	
Over range D	Measured value at terminals D limited by filter setting	Fct. C 2.x.08 Limitation If <u>frequency output:</u> extend values under Fct. C 2.x.05 and Fct. C 2.x.07.	
Active settings	Fault detected during CRC check of active settings	Upload Backup 1 or Backup 2 settings, check and adjust if necessary.	
Factory settings	Fault detected during CRC check of factory settings		
Backup 1 / 2 settings	Fault detected during CRC check of Backup 1 / 2 settings	Store active settings in Backup 1 / 2.	
Status: U (see texts below)	 uncertain flow measurement, measure- ment continues, accuracy possibly less 	Maintenance necessary!	
uncertain measurement	uncertain flow measurement, measurement continues with less accuracy	Group message, when faults as below or other influences occur.	
Pipe not full (applies only to primary heads with 3 or 4 electrodes, Option)	Full-pipe electrode (Option) is not in contact with the medium. Monitoring / message only plausible when the lowest appropriate electrical conductivity is set under Fct. C 1.3.03 Full Pipe = "on" and under Fct. C 1.3.04 Limit Full Pipe	Measuring tube not completely filled, error dependent on fill level. If necessary, change wiring! Or: Electrodes completely insulated e.g. by oil film. Clean!	

Display messages	Description	Possible causes, remedial action	
Status: U (cont´d)	 uncertain flow measurement, measurement continues, measured values uncertain 	Maintenance necessary!	
Empty pipe	1 or 2 measuring electrodes are not in contact with the medium. Display can assume arbitrary values! Monitoring / message only when "cond.+ empty pipe [U]"is activated under Fct. C 1.3.01 Empty Pipe	Filling level of EMF less than 50% or electrodes completely insulated. If "0" to be indicated when pipe is empty, activate under Fct. C 1.3.01 "cond.+empty pipe [A]".	
Linearity	Measured values at both field current levels are not equal. Monitoring / message only after input of Fct. C 1.3.05 Linearity "on" and in Fct. C 1.1.03 GK values "GK+GKL" and the GK and GKL values on the nameplateof the primary head in Fct. C 1.1.04.	Very strong external magnetic fields, or defect in sensor´s magnetic circuit or in signal processing	
Flow profile	Disturbed flow profile , flow continues to be indicated. Monitoring / message only when "on" is activated under Fct. C 1.3.08 Flow Profile	Unimpeded inlet and outlet runs of sensor too short, Pipeline not fulll Measuring tube liner damaged.	
Electrode noise (not when pipe empty)	Electrode noise too high, flow measurement continues, mA and display indication possibly noisy. Monitoring / message only if Fct. C 1.3.09 Electrode Noise is activated, and Fct. C 1.3.10 Limit Noise has been set.	 a) Electrodes extremely soiled b) Conductivity too low c) Gas bubbles, solids or chem. reactions in medium d) Electrode corrosion (if message also appears when flow is zero) To b), c): activate noise or pulse filter Fct. C 1.2.04, C 1.2.07, To b): EMF poss. unsuitable To d): use sensor with suitable electrode material 	
Gain error	Preamplif. not equal to calib. value. Measuring error possible. Message only when Fct. C 1.3.01 Gain activated	Defect: replace electronic unit!	
Electrode symmetry	Impedance of measuring electrodes not equal, Monitoring / message only if Fct C 1.3.01 Conductivity (also[A] or.[U]) activated.	Deposits in measuring tube or electrode short circuit to ground. Clean and check measuring tube!	
Field coil broken	Coil resistance too high, indication poss. zero.	Check field current connections to	
Field coil bridged	Coil resistance too low, indication poss. zero	electronic module (in separate versions: the field current cable) for break / short circuit	
Field current deviation (not when coil broken)	Field current not equal to calib. value, Monitoring / message only if Fct. C 1.3.07 Field Current activated	Check field current connections; if OK: electronics defective, replace electronic unit.	
Field frequency too high	Magnetic field does not settle properly.	If Fct. C 1.1.14 Settling Time set to "Manual", increase value in Fct. C 1.1.15. If "Standard" is set, set field frequency in Fct. C 1.1.13 acc. to sensor nameplate.	
Electronic temperature	Temperature of electronic equipment too high. Impairs service life (reliability)!	Ambient temperature too high, direct solar radiation or, for C Version, process temp. too high.	
Field coil temperature (not when coil broken)	Coil temperature too high	Process temperature and ambient temperature too high	
Overflow, counter 1 / 2	Counter has overrun and started again at zero.		
Backplane invalid	The data record on the backplane is invalid. The CRC check has revealed a fault.		

Display messages	Description	Possible causes, remedial action	
Status: C (see texts below)	= Output values in part simulated or fixed		
Checks in progress	Testing mode by invoking test or simulation functions, All or some outputs not available, Measured values may poss. be simulated	Message via HART or FDT, as the case may be. Indic. via the display when outputs held by control input or have been set to zero	
Test XXXXX (see texts below)	Test of relevant unit activated		
Status: I (see texts below)	= Information (current measurement OK)		
Counter 1 stopped	Counter 1 has stopped counting	If counter to continue counting,	
Counter 2 stopped	Counter 2 has stopped counting	activate "yes" in Fct. C 2.y.09 Start Counter	
Line failure	Indicates that the device was out of service for an unknown period due to a power failure	Cause: temporary line failure, during which counters stopped counting.	
Control input A active	Message appears when the control input at	This message is for information	
Control input B active	terminals A or terminals B is active.	only	
Over range Display 1	1st line on page 1 and/or 2 of display limited by	Menu Display Fct. C 4.3 and/or	
Over range Display 2	filter setting, indication not correct	C 4.4, select Meas. Page 1 or 2, and increase values in Functions C 4.z.03 Meas. Range and/or C 4.z.04 Limitation	
Backplane, sensor	The sensor data on the backplane are no use because they have been generated with an incompatible version.		
Backplane settings The global settings on the backplane are no because they have been generated with an incompatible version.			
Backplane difference The data on the backplane differ from the data the display. If the data can be used, a dialogu indicated in the display.			
Optical interface	The optical interface is in use. The keys on the local display are inoperative.	Keys are ready to operate again 60s after end of data transfer / removal of the optocoupler	

5 Technical data

5.1 IF Versions	C 300 signal		
<u>Standard</u>	IFC 300 C IFC 300 F IFC 300 W IFC 300 R		Compact version Field housing version Version for wall mounting 19" rack version
<u>Option</u>	Interfaces (for IFC 300 _ / BC	,	Fieldbus Foundation and PROFIBUS PA and DP for Batch Control applications
	EEx versions: Approvals:	ATEX FM CSA TIIS Aus Volumetric meter for custody transfer	EEx Zone 1 d + e + i and EEx Zone 2 Class I DIV 1 + 2 GP / Class I DIV 1 + 2 Zone 1 + 2 Ex Zone 1 + 2 cold water: OIML R 49 and KIWA BKR 618/4 excl. water: OIML R 117
Measuren Measured		Units	in metric, British or in US units
		Volume flow rate	Full-scale range $Q_{100\%}$ settable as required from approx. 5 l/h - 400 000 m ³ /h,equivalent to 220 - 1 800 000 US gal/min (dependent on meter size) for electrical conductivities of the process product from \geq 1 µS/cm (\geq 20 µS/cm for demineralized water)
		Flow velocity	settable as required from 0 - 15 m/s equivalent to 0 - 50 ft/s (both directions)
		Mass flow rate	derived from volume flow rate at known and constant density (settable from 100 - 5000 kg/m ³ equivalent to 0.8340 - 41.73 lb/gal)
		Electrical conductivity	settable as required from approx. > 0 to \leq 10000 $\mu S/cm$
		Temperature	in sensor, settable as required from -40 to +200°C / -40 to +392°F
Diagnosti	c functions	Standards	meets and exceeds VDI / NAMUR / WIB 2650
		<u>Messages</u>	Output of messages optionally via display, current and/or status output, and also HART [®] or bus interface
		Accuracy and function	Monitoring of µP and memory, field current, limit overshooting, temperature of electronic equipment, accuracy of signal processing, signal and field current cables, break or short circuit, and load and open circuit of current output
		<u>Application</u>	Monitoring of correct installation (flow profile, inlet and outlet runs), Monitoring for: empty measuring tube (partial filling), conductivity to low, electrode short circuit, electrode insulation or corrosion, gas bubbles (cavitation), solids, temperature of field coils, and damage to the liner

5.1 IFC 300 signal converter

Display and operator control			
Type		Graphic display (backlit – white)	
		128 × 64 pixels / 59 × 31 mm	
<u>Display functions</u>		 3 pages (page through with ↑) pages 1 / 2: optionally with one to three lines. Each line can be used to show current volume / mass flow rate, other measured variables or counts In a 2-line setting, the measured variable in the 1st line can be shown in the form of a bar graph in the 2nd line. Display ranges and number of places freely selectable. Page 3: List of diagnostic and status messages 	
<u>Units</u>		metric, British and US units, selectable from lists for volumetric and mass flow rates, flow velocity, electrical conductivity, temperature, volume, mass and density	
Counter places		Max. 8	
Language of display texts		English, German, French, others on request	
Operating elements		4 optical keys ($\rightarrow \downarrow \downarrow \uparrow$) for operator control of the signal converter without opening the housing	
		Infrared interface for reading and writing all parameters with KROHNE IR-Interface without opening the housing	
Output / input assemblies		For number and possible combinations of the various outputs and inputs, refer to Sect. 2.2	
Current output			
<u>Function</u>		 Volume and mass flow rate, flow velocity, field coil temperature or electrical conductivity 	
		 HART[®] interface is standard (but not for all option modules), see Sect. 2.2 	
		 active or passive operation, dependent on the output / input assemblies, see Sect. 2.2 	
Op. values and load rating	active	$I \le 22 \text{ mA} / R_L \le 1 \text{ k}\Omega$	
	passive	$I \leq 22 \text{ mA} / \text{U} \leq 32 \text{ V DC}$	
Current		Measuring range I_{min} - I_{max} between 0 - 20 mA settable as required	
Overrange		Setting: 0.00 mA \leq value \leq 21.5 mA	
Error identification		0 mA \leq I_{Err} < I_{min} or $$ I_{max} < I_{Err} \leq 22 mA	
Forward / reverse measurement		Direction identified via status output, see below	
Automatic range or external rang	e	via status output or control input, see below	
Time constant		0 - 100.0 s, settable as required	
Low-flow cutoff		Value: 00.0 - 20.0 % of Q _{100%} , settable as required Hysteresis: ± 00.0 - 20.0 %. I required	

Pulse / frequency output					
Function		 When set as frequency output: volume, mass, flow velocity, coil temperature or electrical conductivity When set as pulse output: volume, mass (e.g. 1 pulse / m³ or / kg) 			
		 active or passive mode, dependent on the output / input assemblies, see Sect. 2.2 			
Op. values and load rating	active	f ≤ 10 kHz: l ≤ 20 mA $~/~$ f ≤ 100 Hz: l ≤ 100 mA U_{nom} 24 V DC / U_0 1.5 V @ 10 mA			
	passive	$f \leq 10$ kHz: $I \leq 20$ mA $\ /$ $\ f \leq 100$ Hz: $I \leq 100$ mA U ≤ 32 V DC / U_0 ≤ 1.5 V @ 10 mA			
	NAMUR	to EN 60947-5-6 (operating data as for "passive")			
Pulse rate		0 - 10 kHz, scalable (overflow up to $f_{\text{max}} \leq$ 12 kHz)			
Pulse width		0.05 - 2000 ms (autom., symm. or settable)			
Forward / reverse measuremer	<u>nt</u>	Direction identified via status output, see below			
Time constant		0 - 100.0 s, settable as required			
Low-flow cutoff		Value: 00.0 - 20.0 % Hysteresis: ± 00.0 - 19.9 %.] of Q _{100%} , settable as required			
Status output					
<u>Function</u>		 limit switch, empty pipe, polarity sign, overrange, automatic range, counter preset, failure, maintenance requirement, adjustable to inverse operation active or passive operation, dependent on 			
		output / input assemblies, see Sect. 2.2			
Op. values and load rating	active	$U \leq 24$ V DC/ I ≤ 100 mA $\ / \ U_0 \leq 1.5$ V @ 10 mA			
	passive	$U \le 32 \text{ V DC/ I} \le 100 \text{ mA} / U_0 \le 1.5 \text{ V} @ 10 \text{ mA}$			
	NAMUR	to EN 60947-5-6 (operating data as for "passive")			
Time constant		0 - 100.0 s, settable as required			
Control input Function		 hold outputs, set outputs to zero, counter reset, error reset, range change, operating state: (off) active or passive operation, dependent on output / input assemblies, see Sect. 2.2 			
Op. values and load rating	active	I _{nom} = 16 mA / U _{nom} = 24 V DC			
	passive	$U \leq 32~V~DC$ / U_{on} > 19 $V~DC$ / U_{off} < 2.5 $V~DC$			
	NAMUR	to EN 60947-5-6 (operating data as for "passive")			
Internal electronic counters		2, settable independent of one another			
Measured variable		Volume or mass flow rate			
Function		Sum + or – counter and preset counter			
Time constant		0 - 100.0 s, settable as required			
Low-flow cutoff		Value: 00.0 - 20.0 % Hysteresis: ± 00.0 - 19.9 %.] of Q _{100%} , settable as required			

Electrode circuit					
Terminals		Term. 1, 2, 3, 4 and 20, 30, 40 (not provided in Compact Version C)			
Field current supply					
Type		bipolar pulsed DC field for			
Туре		bipolar pulsed DC field for all KROHNE sensors (primary heads), galvanically separated from all input and output circuits			
Terminals		Term. 7, 8 and 9			
		(not provided in Compact Version C)			
Current / voltage		$\pm 0.125 \text{ A} \ (\pm 5 \ \%) \qquad U_N \leq 40 \text{ V}$			
Clock frequency		$^{1}/_{36}$ up to 2 x power frequency, settable acc. to the calibration data of the sensor			
Power supply		AC Version	DC Version		
Voltage range (without c	:hangeover)	100 - 230 V AC	12 - 24 V DC		
Tolerance band	inaligeover)	-15% / +10 %	-25 % / +30 %		
Frequency		48 - 63 Hz	-		
Power consumption (incl	,	≤ 22 VA	≤ 12 W		
	unctional extra-low voltage (12 - 24 (to VDE 0106 and IEC 364 / 536 d				
Housing					
<u>Materials</u>	• C Compact:	die-cast aluminium (optiona	•		
	• F Field housing	die-cast aluminium (optiona	ally stainl. steel 1.4404)		
	• W Wall-mounted hsg	polyamide			
	• R 19" rack	aluminium section, stainles sheet, in part with polyeste			
Ambient temperature	 in operation 	-40 +65 °C / -40 149	°F		
	 in storage 	-50 +70 °C / -58 to +158	3°F		
Degree of protection					
(IEC 529 / EN 60 529)	C Compact:	IP 67 / NEMA 6			
	• F Field housing	IP 67 / NEMA 6			
	• W Wall-mounted hsg	IP 65 / NEMA 4 and 4X			
	• R 19" rack	IP 20 / NEMA 1			
Cable entry for	Versions C, F and W	M 20 × 1.5, 1/2" NPT or PI	F 1⁄2"		
Signal cables KROHNE DS 300 (stand 	dard)	double shield, signal cable	A, standard length 5 m		
• KROHNE BTS 300 (opti	ion)	triple shield, signal cable B			
other signal cables (note	e following operating data!)	 Low-voltage directives to equivalent national stan Capacitance of signal w wire to wire and wire to signal w vire to wire and w vire to wire to w vire to wire to w vire to	idards ire: shield / ft D GΩ / mile		
		 Voltage checks signal wire / inner shield signal wire / signal wire signal wire / outer shield 	1000 V 1000 V		
		 Twisting / strapping of si minimum 10× / m or 3× important when screeni 	· / ft		

5.2 Selection table for KROHNE sensors (primary heads)

Sensor	Meter size			Special features	EEx-	Custody
	Connection	DN mm	inch		Version (various)	transfer
OPTIFLUX 1000	Sa	DN 10 - 150	³ / ₈ " - 6"	Teflon [®] PFA liner	-	-
OPTIFLUX 2000	FI	DN 25 - 3000	1" - 120"	specifically for water	-	-
OPTIFLUX 4000	FI	DN 2.5 - 3000	¹ / ₁₀ " - 120"	Teflon [®] PFA, ETFE, and others	yes	yes
OPTIFLUX 5000	Sa	DN 2.5 - 100	¹ / ₁₀ " - 4"		yes	yes
	FI	DN 150 - 250	6" - 10"	ceramics, 99.7 % Al ₂ O ₃		-
OPTIFLUX 6000	Food	DN 2.5 - 150	¹ / ₁₀ " - 6"	Teflon [®] PFA liner	yes	_
	1000	DN 2.5 - 150	7 ₁₀ - 0	hygienic use		

Sa Sandwich design, flangeless

FI Flanged design

Food hygienic screw, clamp and flange connections

5.3 Flow tables

v = flow velocity in m/s


Full scale range Q _{100%}		Meter s	Meter size in		Full scale range Q _{100%}		
v = 0.3 m/s	v = 1.0 m/s	v = 12 m/s	DN mm	inch	v = 1.0 ft/s	v = 10 ft/s	v = 40 ft/s
minimum		maximum			minimum		maximum
0.0053	0.0177	0.2121	2.5	¹ / ₁₀	0.0237	0.2372	0.9486
0.0136	0.0452	0.5429	4	¹ / ₈	0.0607	0.6071	2.428
0.0306	0.1018	1.222	6	1/4	0.1366	1.366	5.464
0.0849	0.2827	3.392	10	³ / ₈ ¹ / ₂	0.3794	3.794	15.18
0.1909	0.6362	7.634	15	¹ / ₂	0.8538	8.538	34.15
0.3393	1.131	13.57	20	³ / ₄	1.518	15.18	60.71
0.5302	1.767	21.20	25	1	2.372	23.72	94.86
0.8686	2.895	34.74	32		3.886	38.86	155.4
1.358	4.524	54.28	40	1 ¹ / ₂	6.071	60.71	242.8
2.121	7.069	84.82	50	2	9.486	94.86	379.4
3.584	11.95	143.3	65	-	16.03	160.3	641.3
5.429	18.10	217.1	80	3	24.28	242.8	971.4
8.483	28.27	339.2	100	4	37.94	379.4	1 518
13.26	44.18	530.1	125	-	59.29	592.9	2 372
19.09	63.62	763.4	150	6	85.38	853.8	3 415
33.93	113.1	1 357	200	8	151.8	1 518	6 071
53.02	176.7	2 120	250	10	237.2	2 372	9 486
76.35	254.5	3 053	300	12	341.5	3 415	13 660
135.8	452.4	5 428	400	16	607.1	6 071	24 284
212.1	706.9	8 482	500	20	948.6	9 486	37 944
305.4	1 018	12 215	600	24	1 366	13 660	54 640
415.6	1 385	16 625	700	28	1 859	18 593	74 371
542.9	1 810	21 714	800	32	2 428	24 284	97 138
662.8	2 290	26 510	900	36	3 074	30 735	122 940
848.2	2 827	33 929	1 000	40	3 794	37 944	151 778
1 221	4 072	48 858	1 200	48	5 464	54 640	218 560
1 663	5 542	66 501	1 400	56	7 437	74 371	297 484
2 171	7 238	86 859	1 600	64	9 714	97 138	388 551
2 748	9 161	109 931	1 800	72	12 294	122 940	491 760
3 393	11 310	135 717	2 000	80	15 178	151 778	607 111
4 105	13 685	164 217	2 200	88	18 365	183 651	734 605
4 866	16 266	195 432	2 400	96	21 856	218 560	874 240
5 734	19 113	229 361	2 600	104	25 650	256 504	1 026 018
6 650	22 167	266 005	2 800	112	29 748	297 484	1 189 938
7 634	25 447	305 363	3 000	120	34 150	341 500	1 366 000

v = flow velocity in ft/s

Teflon[®] is a registered trademark of DuPont.

5.4 **Measuring accuracy / error limits** (under reference conditions, see below)

All KROHNE EMFs are calibrated by direct volumetric comparison on internationally traceable calibration rigs accredited in conformity with EN 17025.



OPTIFLUX sensors	DN [mm]	[inch]	Measuring error	Curve
5300	10-100	³ / ₈ " - 4"	0.15% of M.V. + 1mm/s 0.04"/s	1
	150 - 250	6" - 10"	0.2% of M.V.+ 1mm/s 0.04"/s	2
2300 / 4300	10 - 1600	³ / ₈ " - 64"		2
6300	10 - 150	³ / ₈ " - 6"	0.2% of M.V.+ 1mm/s 0.04"/s	
1300	10 - 150	³ / ₈ " - 6"		
4300 / 5300 / 6300	2.5 - 6	¹ / ₁₀ " - ¹ / ₄ "	0.3% of M.V.+ 2mm/s	3
2300 / 4300	> 1600	> 64"	0.08"/s	


Reference conditions similar to those in EN 29 104


Process product	water at 10 – 30°C / 14 … 86°F
Electrical conductivity	> 300 µS/cm
Power supply	$U_N \pm 2\%$ (U_N = rated voltage)
Ambient temperature	18 – 28°C / 65 -82°F
Warm-up time	approx. 10 min
Calibration equipment	max. uncertainty < 0.2 x F
Inlet / outlet runs	equiv. to 10 x DN / 2 x DN (DN = meter size)
Primary head	properly grounded and centered


Special calibrations on request


Every single KROHNE signal converter undergoes a burn-in test for a minimum of 20 hours at varying ambient temperatures from -20 to +60°C / -40 to +149°F. Functioning and accuracy of each signal converter are monitored by computer.

5.5 Dimensions and weights IFC 300 signal converter










Use rectangular cutouts. Clips may not extend through mounting plate more than max. 10 mm. = 0.4°



Several IFC 300 F mounted side by side

When all mounted on one level: centre-to-centre distance of mounts: $\geq 600 \text{ mm} / \geq 23.6^{\circ}$, so as to allow easy access to terminal compartment for power and outputs.

Recommended for larger number of IFC 300 F meters: staggered arrangement laterally and vertically (e.g. vertical spacing of mounting plates \ge 250 mm / \ge 9.8")

Returning a device for testing or repair to KROHNE

This device has been carefully manufactured and tested. If installed and operated in accordance with these operating instructions, it will rarely present any problems. Should you nevertheless need to return a device for inspection or repair, please pay strict attention to the following points:

Due to statutory regulations on environmental protection and safeguarding the health and safety of our personnel, KROHNE may only handle, test and repair returned devices that have been in contact with products without risk to personnel and environment.

This means that KROHNE can only service this device if it is accompanied by the following certificate confirming that the device is safe to handle.

If the device has been operated with toxic, caustic, flammable or water-endangering products, you are kindly requested:

- · to check and ensure, if necessary by rinsing or neutralizing, that all cavities are free from such dangerous substances,
- to enclose a certificate with the device confirming that is safe to handle and stating the product used.

We cannot service this device unless accompanied by such a certificate.

SPECIMEN certificate					
Company:		Address:			
Department:		Name:			
Tel. No.:		Fax No.:			
The enclosed device					
Туре:					
KROHNE Order No. or S	eries No.:				
has been operated with t	•				
Because this liquid is	O water-hazardous	O toxic	O caustic	O flammable	
we have O checked that all cavities in the instrument are free from such substances O flushed out and neutralized all cavities in the device					
We confirm that there is no risk to humans or environment through any residual liquid contained in this device.					
Date:	Signature:				

Company stamp: