Onset Computer Corporation

Full Cross Arm Kit Packing List

(part # M-CAA)

	Qty	√	Item(s)
A	1		Full Cross Arm
B	2		¼-20 x 2 ¾" Hex Head Bolts
C	4		¼" Stainless Steel Flat Washers
D	4		¼-20 Nuts
E	2		½-20 x 1 ¾" Hex Head Bolts
F	1		Mast Plug
G	4		¼" split Lock Washer

Additional Information

Refer to the sensor manual and/or station manual for assembly and operating instructions. For further information, please contact your place of purchase: Onset Computer Corporation or an Authorized Onset Dealer.