


Hauptmenü
Main menu


Messmodus: Messungen durchführen
(mit angeschlossenem Fühler oder integriertem Luftdrucksensor)

Archiv: Archivierte Messwerte aufrufen

Einstellungen: Geräteeinstellungen vornehmen

Measuring mode: Carry out measurements
(with connected probe or integrated air pressure sensor)

Archive: Open archived measurements

Settings: Change device settings

Messmodus
Measuring mode


- 6** Auswahl der jeweiligen Messgröße
7 Messperiode für MIN, MAX, AVG bzw. HOLD zurücksetzen
8 Darstellung der Messwerte festlegen:
 Minimum: Kleinsten ermittelten Messwert (MIN) einer Messperiode anzeigen
 Maximum: Größten ermittelten Messwert (MAX) einer Messperiode anzeigen
 Durchschnitt: Durchschnittswert aller ermittelten Messwerte einer Messperiode anzeigen
9 Halten: Aktuell ermittelten Messwert (HOLD) halten und dauerhaft anzeigen
10 Aus: Anzeige der Messwerte ausschalten

Halten: Aktuell ermittelten Messwert (HOLD) halten und dauerhaft anzeigen

Aus: Anzeige der Messwerte ausschalten

- 9** Für die Dauer eines zuvor bestimmten Aufzeichnungsintervalls eine automatische Messung durchführen
10 Aktuell angezeigten Messwert als Einzelmessung mit Zeitstempel und Datum im Archiv speichern.

- 6** Selection of the respective measured value
7 Reset of measuring period for MIN, MAX, AVG or HOLD
8 Specification of how measured values are displayed:

Minimum: Display smallest measured value (MIN) from a measuring period


Maximum: Display largest measured value (MAX) from a measuring period



Average: Display of the average value of all measured values from a measuring period

Hold: Hold and continuously display the current measured value


Off: Switch-off of the display of measured values

- 9** Perform automatic measurement for the duration of a previously specified recording interval
10 Save currently displayed measured value as single measurement in the archive with date and time stamp.

Micro-USB-Kabel verbinden
Micro-USB cable connection




Bedienelemente
Operating elements



1 back 2 control cross
3 illumination on/off 4 OK 5 main menu

Bedienungsanleitung:



www.epluse.com/omniport30_manual_de.pdf

Manual:



www.epluse.com/omniport30_manual_en.pdf

PC-Software SmartGraph3:
www.epluse.com/smartgraph3

